



Peugeot 2008 (UKL): 2DPS651

Vinnumber:	VR3USHN5SPJ582875	Versionname:	2008 Active Pack 1.2 Puretech S&S 130pk/cv 5p EAT8
First Registrationdate:	17/05/2023	Fiscalpower:	
Expertise Mileage:	37515	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/65/16/98 H				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				215/65 R 16 98 H
Tyre size FR				215/65 R 16 98 H
Tyre size RL				215/65 R 16 98 H
Tyre size RR				215/65 R 16 98 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	No	Compressor	Yes
------------	----	------------	-----

Engine insulation, Damaged, Replace



Bonnet, Stone chip(s), Acceptable



Windscreen, Repaired, Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Tyre repair kit, Missing, Check



Bumper moulding R, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Spot repair



Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Kenteken	2DPS651
Merk Model	Peugeot 2008 Active Pack 1.2 Puretech S&S 130pk/cv 5p EAT8
Brandstofsoort	Benzine
Datum deel1	5/17/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/16/26	35,052	bougie	Vervangen
6/16/26	35,052	luchtfilter	Vervangen
6/16/26	35,052	luchtfilter interieur	Vervangen
6/16/26	35,052	oliezeef	Vervangen
6/16/26	35,052	onderhoud 3e jaar	Uitvoeren
6/16/26	35,052	ruitwisserrubber achter	Vervangen
6/16/26	35,052	ruitwisserrubber vooraan	Vervangen
6/13/25	20,408	luchtfilter interieur	Vervangen
6/13/25	20,408	oliezeef	Vervangen
6/13/25	20,408	onderhoud 2e jaar	Uitvoeren
6/13/25	20,408	remvloeistof	Bijvullen/-laden
6/13/25	20,408	ruitwisserrubber achter	Vervangen
6/13/25	20,408	ruitwisserrubber vooraan	Vervangen
5/8/24	9,546	luchtfilter interieur	Vervangen
5/8/24	9,546	oliezeef	Vervangen
5/8/24	9,546	onderhoud 1e jaar	Uitvoeren