



Opel Corsa: K557BF

Vinnumber:	VXKUHZKXZL4383622	Versionname:	Corsa-E 100kW / 50kWh Elegance
First Registrationdate:	18/11/2020	Fiscalpower:	
Expertise Mileage:	51535	Power Kw:	100
Bodytype:		Body colour:	Summit White lak
Gearbox:	Automatic	Paint type:	Opaque
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	503
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	3	Lining semi-leather
GPS		
Autom climate control		
Radio multimedia		


Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Aluminium	7,1 mm	Vredestein	All season
	Right	195 / 55 / 16 / 87 / H / Aluminium	7,2 mm	Vredestein	All season
Rear	Left	195 / 55 / 16 / 87 / H / Aluminium	4,8 mm	Vredestein	All season
	Right	195 / 55 / 16 / 87 / H / Aluminium	5,0 mm	Vredestein	All season

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Interior covering A pillar L, Broken, Smart repair



Interior, Stain, Cleaning



Bonnet, Chemical polution, Polish



Bumper R, Crack, Repair and paint (complete)



Rear window, Scratch(es), Replace



Bodywork, Chemical polution, Polish



Kenteken	K557BF
Merk Model	Opel Corsa-E 3 fase lader 100kW / 50kWh Elegance
Brandstofsoort	Elektrisch
Datum deel1	18-11-20

Datum reparatie	Kilometerstand	Reparatie omschrijving
06-10-25	48.319	Vervanging band
18-10-24	33.720	APK
18-10-24	33.720	Raam mechanisme
18-10-24	33.720	Tractie batterij lader
20-09-24	33.720	High Voltage lader aansluiting
29-01-24	26.724	Onderhoudsbeurt
31-08-23	0	Accu
17-08-23	21.635	Onderhoudsbeurt
17-08-23	21.635	Remvloeistof
17-08-23	21.635	Tanklepmotor
02-08-23	0	Accu
18-04-23	19.553	Accu
18-04-23	19.553	Onderhoudsbeurt
15-09-22	0	Accu
29-06-22	12.166	Onderhoudsbeurt
29-06-22	12.166	Reparatie band(en)
16-12-21	4.297	Onderhoudsbeurt