MACADAM










Citroen C3: HDT93V

Vinnumber:	**VR7CCHPV7ST004629**	Versionname:	**C3 1.2 PureTech 74kW S&S Max**
First Registrationdate:	**11/02/2025**	Fiscalpower:	
Expertise Mileage:	**75938**	Power Kw:	**74**
Bodytype:		Body colour	**Perla Nera Black metallic**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**479**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**1**	Lining semi-leather	
GPS		Rear parking sensors	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 50 / 17 / 93 / W / Aluminium	7,2 mm	Goodyear	Summer
	Right	205 / 50 / 17 / 93 / W / Aluminium	6,9 mm	Goodyear	Summer
Rear	Left	205 / 50 / 17 / 93 / W / Aluminium	7,5 mm	Goodyear	Summer
	Right	205 / 50 / 17 / 93 / W / Aluminium	7,7 mm	Goodyear	Summer

Assistance equipment

Ignition key, Missing, Replace

No pictures to display

Interior, Stain, Cleaning






Door FL, Dent(s), Repair and paint (complete)





Outside rear-view mirror housing L, Scratch(es), Polish




Wing RL, Dent(s), Paintless dent repair





Windscreen, Stone chip(s), Windscreen repair





Bumper F, Dent(s) and scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Repair and paint (complete)





Door RR, Bad repair, Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Polish




Roof pillar R, Scratch(es), Repair and paint (complete)




Boot cover, Missing, Replace



Rear spoiler, Chemical polution, Polish




Onderhoudshistorie van: VR7CCHPV7ST004629

ALPHABET

Kenteken	HDT93V
Merk Model	Citroen C3 1.2 PureTech 74kW S&S Max
Brandstofsoort	Benzine
Datum deel1	2/11/25

Datum reparatie	Kilometerstand	Reparatie omschrijving
7/22/26	0	Accu
7/8/26	73,183	Onderhoudsbeurt
5/2/26	0	Accu
2/4/26	54,142	Bougie
2/4/26	54,142	Luchtfilter
2/4/26	54,142	Onderhoudsbeurt
10/30/25	43,862	Bougie
10/30/25	43,862	Onderhoudsbeurt
8/5/25	25,234	Reparatie band(en)
7/15/25	19,712	Onderhoudsbeurt
3/26/25	6,364	Sleutel/Kaart
3/26/25	0	Sleutel/Kaart