



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Overview


Order number: 1002400810
Order completed: 14.04.2026 14:38
Report number: 10424208
VIN: WVVZZZCD3RW031804



Front Left 3/4



Rear Right 3/4



Mileage



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	Limousine
Make:	Volkswagen
Model:	Golf
Manufacturers and type code:	0603 / CPJ
Date of first registration:	24.01.2024
Mileage:	20,994 km
Proof of mileage:	ReadOff
Exterior colour:	Mondsteingrau
Roof colour:	Mondsteingrau
Propulsion:	Front
Fuel:	Petrol
Engine size (cc):	1,500 ccm
Performance:	96 kW (131 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	5
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining Alcantara
Interior colour:	Soul-Schwarz/Soul-Schwarz/Schwarz/ Storm Grey
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	No
Registration certificate received:	No
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	0 Day(s)



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

<p>"Ventura" 7.5J x 17, tires 225/45 R17</p> <p>12-V outlet in luggage compartment</p> <p>2 LED reading lights in front and 2 in rear</p> <p>2 USB-C ports in the front, 2 USB-C charging sockets on the center console in rear, charging capacity up to 45 W</p> <p>3 head restraints in rear</p> <p>30-color ambient lighting</p> <p>3-point seat belts for the outer rear seats</p> <p>3-point seat belts in front with height adjustment and seat belt pretensioners</p> <p>4 alloy wheels "Ventura" 7.5J x 17</p> <p>4-cylinder SI engine 1.5 l</p> <p>4-cylinder SI engine 1.5 l TSI, Miller cycle, 96 kW</p> <p>6+1 speakers</p> <p>7-speed automatic transmission or dual-clutch transmission DSG, note: PR family EDF</p> <p>Activated carbon canister (Evaporative Emission Control System (EVAP))</p> <p>Adaptive Cruise Control ACC stop & go incl. speed limiter</p> <p>Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear</p> <p>App-Connect Wireless for Apple CarPlay and Android Auto</p> <p>Auto. Emergency Braking Front Assist with Pedestrian and Cyclist Monitoring</p> <p>Automatic headlight control with LED separate daytime running light and entry and exit lighting</p> <p>Automatically-heated washer nozzles in front</p> <p>Basic equipment variant</p> <p>Battery 380 A (59 Ah) EFB+</p> <p>Belt-driven integrated starter alternator 48 V 110 - 250 A</p> <p>Body-colored bumpers, air intake with chrome fin</p> <p>Body-colored exterior mirror housings and door handles</p> <p>Business Premium package incl. navigation system "Discover Media"</p> <p>Car2X</p> <p>Carpet mats in front and rear</p> <p>Chrome elements on power mirror and window regulator switches, chrome trims on the vents</p> <p>Chrome trim on the side window bottoms</p> <p>Comfort drive Travel Assist, lane keeping system Lane Assist and Emergency Assist</p> <p>Cornering light and poor weather light</p> <p>Curtain airbags in front and rear, side airbags in front, center airbag</p> <p>Decorative inserts "New Brushed Dark Metal" for dashboard and door trim panels in front</p> <p>Delivery "Autostadt Wolfsburg"</p> <p>Digital radio reception DAB+</p> <p>Dimming interior rearview mirror</p> <p>Disc brakes in front</p>	<p>Disc brakes in rear</p> <p>Diversity antenna for FM reception</p> <p>Door and side trim panel</p> <p>Driver alert system</p> <p>Driver and front passenger airbag with front passenger airbag deactivation</p> <p>Driving on the right</p> <p>Dual-clutch transmission DSG DQ200</p> <p>Dynamic headlight range control</p> <p>Dynamic Road Sign Display</p> <p>Electromechanical parking brake with Auto Hold function</p> <p>Electromechanical speed-sensitive power steering</p> <p>Electronic differential lock XDS</p> <p>Electronic immobilizer</p> <p>Electronic restriction of top speed</p> <p>Electronic Stability Control and electromechanical brake booster</p> <p>Elimination of nameplate for engine designation on luggage compartment lid</p> <p>Emergency call service, 10-year contract duration as of initial delivery, condition: mob. phone network available</p> <p>Emission standard EU6 AP</p> <p>Equipment options subset for Germany</p> <p>ergoActive driver seat with power adjustment, memory feature and adjustable thigh support</p> <p>Ext. mirrors, power-adjustable and heated, with memory feature and front passenger ext. mirror lowering function</p> <p>Extended pedestrian protection</p> <p>Exterior mirrors: aspherical on driver side, convex on front passenger side</p> <p>First aid kit, warning triangle and safety vest</p> <p>Front center armrest, height- and longitudinally adjustable</p> <p>Front stabilizer bar</p> <p>Front-wheel drive</p> <p>Fuel system for fuel-injected SI engine</p> <p>Gearshift knob/handle in plastic</p> <p>Hatchback</p> <p>Headliner</p> <p>Heated front seats</p> <p>Hybrid drive system mHEV</p> <p>Illuminated molding between headlamps and illuminated door handle recesses</p> <p>Illuminated vanity mirrors in sun visors</p> <p>Initial standard fuel filling</p> <p>Inserts of front seats and outer rear seats in ArtVelours microfleece</p> <p>Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer</p>
--	--



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

ISOFIX anchors for child seats on outer rear bench seats and on front passenger seat, compatible for i-Size	Sports comfort seats in front
Keyless Start without SAFELOCK	Sports equipment
Laminated safety glass windshield, heat- and sound-insulating	Standard battery/alternator capacity
Leather-wrapped multi-function steering wheel, heated, with shift paddles	Standard climatic zones
LED light unit in front footwell, selectable light color	Standard curb weight range
LED Plus headlamps	Standard electronic engine sound
LED rear combination lamps	Standard engine starter
Left-hand drive	Standard manufacturing sequence
LongLife Service Regime	Standard paint coating
Lumbar supports in front, power- adjustable on driver side, massage feature on driver side	Standard pedal cluster
Manual in German (Germany)	Standard rear axle
Mobile phone interface "Comfort" with inductive charging feature	Standard rear seat release
Multi-color Digital Cockpit Pro, selection of different info profiles possible	Standard roof
Multifunction camera	Start-stop system with regenerative braking
Navigation system "Discover Media" incl. Streaming & Internet	Surround lighting with welcome light
No special edition	Suspension range 05 installation control only, no requirement forecast
No special purpose vehicle, standard equipment	Tailgate/trunk lid unlocking from outside
Non-folding front passenger seat backrest	Tire Mobility Set: 12-volt compressor and tire sealant
Non-smoker's package: Storage compartment and 12-V outlet in front	Tire Pressure Monitoring System
Not hot country	Tires 225/45 R17
Oncoming vehicle braking when turning and swerve support	Tool kit
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Transport protection film (minimum protection) with additional transport protection measures
Operating permit, alteration	Two-tone horn
Operating voltage 12 V	Type approval country Germany
Park Distance Control - warning signals for obstacles in the front and rear	Unsplit rear bench seat, asymmetric split folding backrest, with center armrest
Part set without country-specific prescriptive standard	UWB-capable country and carrier frequency, 433.92 to 434.42 MHz
Preparation for We Connect and We Connect Plus or VW Connect and VW Connect Plus	Vehicle class differentiation -5H0-
Privacy glass for rear side windows and rear window	Vehicles without special upgrade measures
Radio	Voice control
Rear exhaust tailpipe (standard)	Warning signal and warning light for front and rear seat belts not fastened
Rear floor panel module, type 1	Weight range 4 installation control only, no requirement forecast
Rear fog light on one side, back-up light on both sides	Wheel locks with extended theft protection
Rear shock absorption, basic version 1	Wheelbase
Rear view camera system	Windshield wiper intermittent control with light sensor
Refrigerant R1234yf	Without Adaptive Chassis Control
Regional code " ECE " for radio	Without additional front underbody guard
Safety-optimized front head restraints	Without additional tires
Service indicator 30 000 km or 2 years (variable)	Without alcohol interlock
Shock absorption in front	Without auxiliary heater/parking heater
Special identification label for EC for M1 passenger vehicles	Without charging cable
	Without decals and emblems



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

- Without electric motor (hybrid)
- Without extended safety system
- Without fire extinguisher
- Without headlamp washer system, with washer fluid level indicator
- Without head-up display
- Without heat accumulator/auxiliary heater
- Without hill start assist/hill descent control/comfort driving assist
- Without lane change assist
- Without light control
- Without locking and starting systems
- Without mode 3 charging cable
- Without partition
- Without preparation for rotating beacon/siren combination
- Without preparation for two-way radio installation
- Without rear stabilizer bar
- Without roof rails
- Without seat ventilation/massage seat
- Without second battery
- Without special body measures
- Without speed limiter
- Without trailer hitch
- Without UN-ECE cybersecurity & software update



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Nexen	Front	Left	Summer	Aluminium	225/45 R 17 91 W	5.0 mm
Nexen	Front	Right	Summer	Aluminium	225/45 R 17 91 W	5.0 mm
Nexen	Rear	Left	Summer	Aluminium	225/45 R 17 91 W	5.0 mm
Nexen	Rear	Right	Summer	Aluminium	225/45 R 17 91 W	5.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 07.2027

Compressor present: Yes



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Oil change	Maintenance	Execute
2	Service	Maintenance	Execute

» Usage Damages

Nr	Location	Damage type	Repair type
1	Bumper F	Scratch(es)	Acceptable



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Commercial devaluation

Known previous damages:	Yes
Previous damages detectable:	No
Repainting present:	Yes
Repainting professionally executed:	Yes
Paint thickness measurement performed:	Yes - with abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Liability loss		€ 5,200.00
Total without VAT:				€ 5,200.00

PAINTTHICKNESS MEASUREMENT RESULTS

Part	Paint (µm)
Paint thickness Wing RR (µm)	188.0
Paint thickness Door FR (µm)	210.0

At least 3 measurements were carried out per component.



Assessment

Number: 10424208
From: 15.04.2026

- Vehicle Inspection Report -

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVWZZZCD3RW031804

VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Wet

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Remarks

This copy was generated electronically. It is valid without an original signature.



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Commercial Pictures



Front Left 3/4




Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Tools



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR



Wheel RL



Wheel RR



Central console



Engine compartment



Documents



Interior arrangement



Specific equipment



Paint thickness Door FR



Paint thickness Wing RR



Assessment

- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026



History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



Underbody scan



GPS/Radio



Assessment


- Vehicle Inspection Report -

Number: 10424208
From: 15.04.2026

» Devaluation Damages

DEVALUATION FACTORS

1 - Oil change - Maintenance - Execute



2 - Service - Maintenance - Execute



USAGE DAMAGES

1 - Bumper F - Scratch(es) - Acceptable

