MACADAM








BMW X5 xDrive40i: CDAR643

Vinnumber:	**WBACR610309M84789**	Versionname:	
First Registrationdate:	**9/09/2022**	Fiscalpower:	
Expertise Mileage:	**56567**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**3**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**275/35/22/104 Y**			
	Fr.L.	**Continental: 7 mm**	Fr.R.	**Continental: 7 mm**
	Re.L.	**Continental: 7 mm**	Re.R.	**Continental: 7 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**7.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**275/35 R 22 104 Y**
Tyre size FR	**275/35 R 22 104 Y**
Tyre size RL	**315/30 R 22 107 Y**
Tyre size RR	**315/30 R 22 107 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**0**		

Door panel FL, Tear, Replace






Bumper F, Scratch(es), Acceptable




Alloy rim FL polished, Scratch(es), Repair and paint (complete)






Tyre FL, Tear, Replace




Door FL, Dent(s) and scratch(es), Repair and paint (complete)









Central pillar L, Dent(s) and scratch(es), Spot repair




Wing FL, Repaired, Check




Door FL, Repaired, Check




Luggage compartment cover, Missing, Replace




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)







Alloy rim FR polished, Scratch(es), Repair and paint (complete)








Alloy rim RR polished, Scratch(es), Repair and paint (complete)





Door FR, Scratch(es), Acceptable






Door RR, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable

