



Volvo V60: S812NB

| | | | |
|-------------------------|--------------------------|-------------------------|--|
| Vinnumber: | YV1ZZL1V2P2107536 | Versionname: | V60 B5 2.0 MHEV 184kw AWD Ultimate Cross Country automaat |
| First Registrationdate: | 7/03/2023 | Fiscalpower: | |
| Expertise Mileage: | 183995 | Power Kw: | 184 |
| Bodytype: | | Body colour: | Platinum Grey (metallic) |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Hybrid Petrol | Parking lot: | 1093 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | Yes | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining leather |
| GPS | | Sun Roof electric |
| Autom climate control | | Panoramic roof |
| Radio multimedia | | Rear parking sensors |
| | | Rear view camera |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|------------------------------------|--------|---------|--------|
| Front | Left | 235 / 45 / 19 / 99 / V / Aluminium | 4,2 mm | Hankook | Winter |
| | Right | 235 / 45 / 19 / 99 / V / Aluminium | 4,5 mm | Hankook | Winter |
| Rear | Left | 235 / 45 / 19 / 99 / V / Aluminium | 5,7 mm | Hankook | Winter |
| | Right | 235 / 45 / 19 / 99 / V / Aluminium | 5,8 mm | Hankook | Winter |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (rapid charge) | 0 |
|--|----------|

Service, Maintenance, Execute



Bumper trim F, Scratch(es), Replace



Bonnet, Chemical polition, Polish



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



| | |
|-----------------------|---|
| Kenteken | S812NB |
| Merk Model | Volvo V60 B5 2.0 MHEV 184kW AWD Ultimate Cross Country automaat |
| Brandstofsoort | Benzine |
| Datum deel1 | 07-03-23 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|-----------------------------------|
| 01-09-25 | 148.697 | Onderhoudsbeurt |
| 01-09-25 | 148.697 | Volvo Check slijtagedelen |
| 25-08-25 | 148.430 | Reparatie band(en) |
| 23-06-25 | 137.800 | Reparatie band(en) |
| 01-04-25 | 120.511 | Bougie |
| 01-04-25 | 120.511 | Luchtfilter |
| 01-04-25 | 120.511 | Onderhoudsbeurt |
| 01-04-25 | 120.511 | Riem/ multiriem |
| 01-04-25 | 120.511 | Ruitenwischerblad(en) achterzijde |
| 01-04-25 | 120.511 | Ruitenwischerblad(en) voorzijde |
| 01-04-25 | 120.511 | Volvo Check aandrijving |
| 01-04-25 | 120.511 | Volvo Check slijtagedelen |
| 14-10-24 | 91.782 | Onderhoudsbeurt |
| 14-10-24 | 91.782 | Volvo Check slijtagedelen |
| 21-05-24 | 62.874 | Bougie |
| 21-05-24 | 62.874 | Luchtfilter |
| 21-05-24 | 62.874 | Onderhoudsbeurt |
| 21-05-24 | 62.874 | Volvo Check aandrijving |
| 21-05-24 | 62.874 | Volvo Check slijtagedelen |
| 23-10-23 | 32.392 | Onderhoudsbeurt |
| 23-10-23 | 32.392 | Volvo Check slijtagedelen |