

2-FPG-239

2-FPG-239 · Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06 · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FPG-239	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ5RR181109
Model	Arona	Cylinder Capacity	999 ^{cm3}
Model Versions	Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	01-07-2024
Body Type	5 door hatchback	Odometer	76.825 ^{Km}
Color	Black	Numer Of Keys	1
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	85		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Imperial	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	4 ^{mm}	Imperial	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Windscreen – Front

Chipped

Window Repair

No



Damage Part

Damage Type

Notes

Repair
Type

Acceptable

Roof

Small dent(s)

Dakstijl

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor – Right

small dents / small
scratches

Restyle / Touch-up

No



Damage Part
Alloy - Right Front

Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Alloy - Left Front

Damage Type
Damaged

Repair Type
Acceptable

Acceptable
Yes



Damage Part
spoiler FB

Damage Type
Small scratch(es)

Repair Type
Spotrepair

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Broken	Replace & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	Small dent(s)	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Damaged	Vloerbedekking	Cloth Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Left Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Small scratch(es)	Spotrepair	No



Damage Part	Damage Type	Repair Type	Acceptable
Roof	Small scratch(es)	Acceptable	Yes