



**AUDI A3 SPORTBACK:**

Vinnumber:	<b>WAUZZ28V4LA072879</b>	Versionname:	<b>1.0 30 TFSi 85kW</b>
First Registrationdate:	<b>6/05/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>107025</b>	Power Kw:	<b>85</b>
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2210</b>
Fueltype:	<b>Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>No Tow bar</b>
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

<b>205/55/16/92 H</b>				
Summer tyres:	Fr.L.	<b>Semperit: 5 mm</b>	Fr.R.	<b>Semperit: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/55 R 16 92 H</b>
Tyre size FR				<b>205/55 R 16 92 H</b>
Tyre size RL				<b>205/55 R 16 92 H</b>
Tyre size RR				<b>205/55 R 16 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>2477</b>
Tyre make FR				<b>2477</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>133,03</b>
Seat cover FL, Damaged, Acceptable	<b>0,00</b>



Bumper F, Scratch(es), Acceptable 0,00



Wing RL, Bad repair, Check 0,00



Door RL, Dent(s), Acceptable 0,00



Outer sill L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 0,00



Bumper trim R, Scratch(es), Smart repair 0,00



Rear window, Scratch(es), Replace 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Step R, Scratch(es), Acceptable 0,00

