

Vehicle details

VIN	WVGZZZE2Z NP030696	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.4 77kWh 150kW Pro Auto 5d Onze Deal	Maintenance mileage	-
Registration date	25/02/2022	Year	2022	Exterior Color	Gris Laque
Odometer	131 451 km	Engine size	-	Interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	20/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Vehicle charger	✓
Rear parcel shelf	✗
Wireless charger	✗

Technical Document

User manual	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 235/50/20 Summer 4.0 mm



Pirelli 235/50/20 Summer 3.0 mm



Pirelli 235/50/20 Summer 3.5 mm

Pirelli 235/50/20 Summer 3.5 mm

Exterior

3



Part	Alloy wheel 20"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Bumper
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

10



Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

11



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

12



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Rear parcel shelf
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

4



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

Others

2



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info