



**RENAULT CLIO: GG-361-SC**

Vinnumber:	<b>VF1RJA00869054806</b>	Versionname:	<b>RENAULT CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)</b>
First Registrationdate:	<b>2/06/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>47287</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Berline</b>	Body colour:	<b>Light Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Anthracite</b>
Fueltype:	<b>Petrol</b>	Type of rims (mounted):	<b>Steel</b>
Battery functioning:	<b>No</b>	Dashboard color:	<b>Anthracite</b>
Vehicle running:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Steel</b>		
Category:	<b>Passenger Car</b>		

**Options**

Number of keys total	<b>1</b>	Radio	
Number keys remote	<b>1</b>	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	<b>Lining Other</b>
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	<b>Manual climate control</b>		

**Tyres**

<b>195/55/16/87 V</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 80%</b>	Fr.R.	<b>Bridgestone: 85%</b>
	Re.L.	<b>Bridgestone: 40%</b>	Re.R.	<b>Bridgestone: 45%</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>2.5</b>
Tyre profile depth RL				<b>5.5</b>
Tyre profile depth RR				<b>5.2</b>
Tyre size FL				<b>195/55 R 16 87 V</b>
Tyre size FR				<b>195/55 R 16 87 V</b>
Tyre size RL				<b>195/55 R 16 87 V</b>
Tyre size RR				<b>195/55 R 16 87 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>255</b>
Tyre make FR				<b>255</b>
Tyre make RL				<b>255</b>
Tyre make RR				<b>255</b>

**Assistance equipment**

Malfunction indicator, Blinking, Check



Remote ignition key, Missing, Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Wing RL, Dent(s), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror base L, Scratch(es), Replace



Outside rear-view mirror housing L, Scratch(es), Paint



Bumper F, Deformed / Strained, Repair and paint (complete)



Outside rear-view mirror glass R, Broken, Replace



Outside rear-view mirror base R, Broken, Replace



Outside rear-view mirror housing R, Scratch(es), Paint



Side repeater R, Broken, Replace



Door FR, Scratch(es), Paint



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



## Historique Maintenance

Immatriculation: **GG-361-SC**

Date de 1ère immatriculation: **02/06/2022**

Modèle: **Renault CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
30/09/2025	31.725	RENAULT RETAIL GROUP	RECYCLAGE
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
18/09/2024	13.189	GARAGE DE LA MER	REVISION
	0		BALAIS ESSUIE GLACE AV AR
	0		PILE DE CLE RPLT
28/09/2023	3.785	GARAGE DE LA MER	SERENITE