

Audi

AUDI A3 BERLINE (8VM)(04.2016->) 30 TFSI BASIS MOTEUR 1,0 LITRE(S) - 85 KW TFSI 4 PORTES

VIN: WAUZZZ8V2LA072525



Description

Registration number	Registration date	Odometer
	04/05/2020	84057 km
Color	Year	Upholstery
Blanc Glacier Métallisé	2018	-
Number of doors	Number of seats	Generation
4	5	-
CO2	Engine displacement	Gearbox type
139	999	Manual
Engine type	Fuel Type	Number of gears
Combustion	Petrol	6
Drivetrain	Max power	
Front Wheel Drive (FWD)	85 KW	

Vehicle Equipments

Standard

8 speaker(s)	airbag driver side/passenger side	sidebag front
alarm system for seat belts	generator 140 A	immobilizer (electronic)
brake assistant	electronic differential lock (EDS)	transmission 6-speed
body: 4-door	AUX-IN interface (AUX-IN)	Electronic Stability Control (ESP)
tire pressure control system	jack	power steering electromechanical
brake discs rear (272 mm x 10 mm)	Disques de frein AV (288 mm x 25 mm)	rear seat backrest split/folding
model designation with new performance indication	electronic stability control (ESC)	Enjoliveurs pour Armature de pavillon et lècheur de vitre Aluminium
Longlife-Service	interior equipment decorative trim inserts Micro metallic silver	adaptive brake light
rear fog light(s)	turn signal lights LED in exterior mirror integrated	gasoline particulate filter (GPF)
parking brake electromechanical	radiator grille single-frame look	light alloy rims 7x16 (5-spoke, star design)
tire repair kit	rear window heated	window lifter electric
Type of drive: front-wheel drive	Moteur 1,0 litre(s) - 85 kW TFSI Catalyseur (DKRF)	multi-media Interface MMI basic plus / MMI radio plus
low emissions according to emission standard Euro 6d-TEMP	liftgate control automatic	non-smoking package
power outlet (12V outlet) in center console front	preparation mobile phone with Bluetooth interface	seat belt tensioner
electr. brake force distribution (EBD)	exterior mirror aspherical, left	exterior mirror convex, right
exterior mirror vehicle colour	seat covers/upholstery: cloth Index	seats front height-adjustable
standard seats front	Isofix mounts for child seat	floor mats velours
traction control system (ASR)	antilock braking system (ABS)	braking system with recovery system
start/stop system	rear axle: torsion beam	central locking system with remote control
heat protection glazing green-tinted	veh. without sports suspension	

Optional

center armrest front	parking aid front and rear, acoustic and optical with selective display (APS Plus)	kneebag driver side
Audi connect (web-based services)	Batterie 69 Ah	comfort automatic air-conditioning 2-zone
light and rain sensor	windshield with sun-visor strip top	rear lights LED with dynamic flasher
refrigerant R 1234 YF	roof liner cloth, black	windshield washer jets and exterior mirror heated
vanity mirror illuminated	multi-media Interface MMI Navigation	storage and cargo space package
metallic paintwork	Pneus 205/55 R16 ..V	headlight LED
windshield acoustic glass	cruise control (cruise control)	Réservoir à carburant, système de vaporisation renforcé (Réservoir filtre à charbon actif, EVAP)
exterior mirror electrically adjustable and heated, both	interior mirror with automatic dimming	seat heating front
Driver Information System (DIS) (FIS) with colour display	pedestrian protection system	panoramic pop-up roof electric
glazing rear darkened (Privacy Glass)	steering wheel (sport/leather - 3-spokes) with multiple function	daytime running lights LED

Active warning lights

Maintenance indicator

Statement details

Inspection loc

Statement date

16/07/2026

Inspection approval date

17/07/2026

Control

Detected issues

Engine / Sound

✓ Ok

Vehicle leak proofness

✓ Ok

Exhaust / Clarity

✓ Ok

Defects & corrections

#	Element	Defect	Correction
001	Maintenance indicator	Missing	Carry out
			
002	Wing / Back Left ¹	Scratched	Painting
			
003	Rim / Back Right Rim/Tyre diameter : 16 "	Scratched	Repair
			
004	Interior complete / -	Stained	Cleaning
			
005	Rim / Front Right Rim/Tyre diameter : 16 "	Scratched	Acceptable
			

¹ L'aile a déjà été réparé => sur réserve réclamation

Loose Items


- ☐ Toolkit
- ☐ Load cover
- ☒ Conformity certificate
- ☐ Locking wheel nut
- ☐ Remote key
- ☐ Towing hook
- ☐ Cargo net
- ☐ Security Kit
- ☐ Satellite navigation
- ☐ Document holder
- ☐ Charging cable bag
- ☐ First aid kit
- ☐ Slow charging cable (Type 2, Mode 2)
- ☐ Service book
- ☒ Registration certificate
- ☒ Card key
- ☒ Compressor tyre repair kit
- ☐ Hook /Hich ball
- ☐ Safety vest
- ☐ Jack handle crank
- ☐ In-car tools
- ☐ Refill tyre repair kit
- ☐ Remote control
- ☐ Quick charging cable (Type 2, Mode 3)
- ☐ Warranty booklet
- ☒ Registration certificate owner
- ☐ Locking wheel nuts key
- ☐ Jack
- ☒ Spare Key
- ☐ Tyre repair kit complete
- ☒ User manual
- ☐ Rear parcel shelf
- ☐ Spare wheel tyre
- ☐ Triangle

Main set of tyres

Front Left	CONTINENTAL	205 / 55 / 16 / Winter	6 mm
Front Right	CONTINENTAL	205 / 55 / 16 / Winter	6 mm
Back Left	CONTINENTAL	205 / 55 / 16 / Winter	7 mm
Back Right	CONTINENTAL	205 / 55 / 16 / Winter	7 mm

Comments

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right




Odometer



Navigation




Spare Tyre




Vin



Other




Other



Other



Maintenance indicator / Missing




Maintenance indicator / Missing



Wing / Back Left / Scratched



Wing / Back Left / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Interior complete / - / Stained



Rim / Front Right / Scratched



Rim / Front Right / Scratched