# BMW 3 SERIES TOURING

## Vehicle information

| | | | |
|---|---|---|---|
| Brand: | **BMW** | License plate: | **2CDX567** |
| Gearbox: | | Body color: | |
| Model: | **3 SERIES TOURING** | LEVEL: | **WBA6N91030FN11095** |
| Fuel type: | | Power: | **120 kW** |
| Version: | **2.0 320E TOURING** | First registration | **17/06/2022** |
| Mileage: | **147167 km** | Number of doors: | |

## Summary of damages


| | |
|---|---|
| **Before** | 2 |
| **Interior** | 1 |
| **Roof & other** | 1 |

## Commercial photos





































## Options according to the inspector

| | |
|---|---|
| GPS | **Yes** |


## Damages

**Hood**

Claw(s)

LI - Repair and paint (complete)

Before



**Bodywork**


Damaged -

Acceptable.

Roof & other









Damaged **Interior**
- Acceptable
Interior









**Windshield**
Repaired
E - Replace
Before







## Tires

**Front Left**
Summer
Aluminum
225/50/17/98/Y
Pirelli
3.0 mm
**Front Right**
Summer
Aluminum
225/50/17/98/Y
Pirelli
3.0 mm
**Left Back**
Summer
Aluminum
225/50/17/98/Y
Pirelli
3.0 mm
**Rear Right**
Summer
Aluminum
225/50/17/98/Y
Pirelli
3.0 mm

## Controls

| | | | |
|---|---|---|---|
| Category | **Private vehicle** | Registration certificate - home address section | **No** |
| Vehicle registration certificate | **Yes** | Certificate of Conformity | **Yes** |
| Compressor | **P/A** | Vehicle inspection | **OK** |
| Vehicle inspection | **01/04/2027** | Interview | **OK** |
| Interview | **01/06/2027** | Interview | **12000.0** |
| Repair kit | **P/A** | Number of charging cables (220V) | **1** |
| Number of charging cables (fast charging) | **1** | Total number of keys | **2** |
| Charge level | **0** | Factory reset | **Yes, the vehicle has been reset to factory settings.** |
| Type of maintenance log | **Digital interview** | | |

**Information on the content and scope of the inspection report:**

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.