

Opel Corsa 1.5 D Elegance | Cruise | VC | Navi | Clima | Camera | PDC |

Contact Summary

License plate	L-301-HJ	Fuel	Diesel
VIN	VXKUBYHTKM4165996	Transmission	Manual
Brand	Opel	Doors	5
Model	Corsa	Seats	5
Model Type	1.5 D Elegance Cruise VC Navi...	Color	Red
VAT/Margin	VAT	Interior Color	Black
Mileage	159527 Km	Interior Type	Halfleather
Expected mileage	159527 Km	Paint type	
Available per	Direct	NAP status	Logical

Vehicle Details

History

Manufacture year	2021
First registration	27-05-2021 (NL)
Current registration	27-05-2021 (DE)
Imported	No

Model year	04-07-2019 → 31-07-2023
Used as	Normal
Immigration good	No
Vehicle Source	Dealer

Environment

Energy label	B
CO2 emission (NEDC)	106
EU category	Euro 6

Engine & performance

Power	75 kw
Cylinders	4
Engine	1499
Drivetrain	Frontwheeldri...

Financial

BPM deductible	Yes
Gross BPM	€ 4082
Rest BPM	€ 1433

Weights

Empty weight	1065
Towing weight	1200
Wheel base	254

Remark

Features

Specific features

LED headlights

Alloy wheels 16"

Multimedia preparation

Passenger airbag

Passenger seat height adjustable

Radio

Rain sensor

Lane sensor with correction

Leather steering wheel

Steeringwheel adjustable

Power steering speed dependent

Traffic sign detection

Tiredness recognition

Front side airbag(s).

Exterior mirrors electrically adjustable

Exterior mirrors heated

Central locking with remote control

Chrome exterior parts

Cruise control

DAB

Dipped beam automatically

Rear electric windows

Electric windows in front

Electronic Stability Program

Hill hold function

Front head airbag(s).

LED daytime running lights

Rear seat can be folded down in parts

Air conditioning

Alarm class 1 (immobilizer)

Anti blocking system

Apple Carplay/Android Auto

Autonomous Emergency Braking

Tire pressure monitoring system

Driver's airbag

Driver's seat adjustable in height

Interior mirror automatically dimming

Bluetooth

On-board computer

Collision warning system

Packages

Conditions

Optical issues

Paint restoration
Front right screen

Paint restoration
Front right door

Paint restoration
Rear right door

Paint restoration
Rear right screen

Chippings
Bonnet

Restyle dent(s)
Rear right door

Scratch(es)
Roof

Paint crack
Threshold right



Technical inspection & maintenance

Technical inspection 24-10-2026

Maintenance history Incomplete

Last date of maintenance 21-10-2025

Odorless Yes

Keys 1

Driveable Yes

Tyres

AllSeason Good (4/4/6/6)

Owner history

Date	Extra info	Owner	Number Of Days
20-05-2021		Importeur	7
27-05-2021	Eerste toelating Datum deel IA / I	Lease/verhuur	1839
09-06-2026	Laatste tenaamstelling	Autobedrijf	9
24-10-2026	APK vervaldatum		-

Summary



Opel Corsa 1.5 D Elegance | Cruise | VC | Navi | Clima | Camera | PDC |

Licence plate	L-301-HJ	Technical damage	No
Mileage	159527 Km	Optical damage	Yes
Expected Mileage	159527 Km	Nr of Owners	2
Available per	18-06-2026	Used as	Normal
Transmission	Manual	BPM Reclaimable	Yes
Drivetrain	Frontwheeldrive	Catalog	Continuous
Power	75	Lot ID	3dbb0b4c-86f6-...
VAT/Margin	VAT	Date	30-06-2026
NAP status	Logical	Remark	No
Manufacture year	2021		
Imported	No		
Country of origin	NL		