



OPEL Movano: 5984-MMM

Vinnumber:	VXEYCBPFCG037411	Versionname:	Furgón Base L3H2 3.5T 2.2 BlueHDi 103kW furgón 103kW 4P manual
First Registrationdate:	29/12/2023	Fiscalpower:	103kW
Expertise Mileage:	24958	Power Kw:	103kW
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	1	Radio:	1
Number keys remote:	1	Central consol F:	1
Windows electric F:		Rear parking sensors:	1
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

215/70/15/109 S				
Summer tyres:	Fr.L.	Nexen: 4 mm	Fr.R.	Nexen: 4 mm
	Re.L.	Nexen: 4 mm	Re.R.	Nexen: 4 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				4.0
Tyre profile depth RR:				4.0
Tyre size FL:				215/70 R 15 109 S
Tyre size FR:				215/70 R 15 109 S
Tyre size RL:				215/70 R 15 109 S
Tyre size RR:				215/70 R 15 109 S
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				1957072
Tyre make FR:				1957072
Tyre make RL:				1957072
Tyre make RR:				1957072

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

User's manual, Missing, Repair/replace (lump sum)



Service book, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Interior, Damaged, Repair and paint (complete)



Rear light L, Broken, Replace



Wing RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Wing FL, Scratch(es), Paint



Door FR, Scratch(es), Paint



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover RR, Scratch(es), Replace



Bumper R, Scratch(es), Paint



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

