



Ford Kuga: [redacted]			
Vinnumber:	WF0FXXWPMFNL55033	Versionname:	
First Registrationdate:	18/02/2022	Fiscalpower:	
Expertise Mileage:	159722	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2527
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	1	Seats electric F L	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS base	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	HD		
Limited Technical Inspection			
Tyres			
	225/60/18/104 H		
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R. Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R. Michelin: 5 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			225/60 R 18 104 H
Tyre size FR			225/60 R 18 104 H
Tyre size RL			225/60 R 18 104 H
Tyre size RR			225/60 R 18 104 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			3060,14
Ignition key, Missing, Replace			420,10



Bumper F, Scratch(es), Spot repair	148,33
------------------------------------	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------



Wing RL, Dent(s), Paintless dent repair	95,47
---	-------



Wing trim RL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Door RL, Scratch(es), Spot repair	148,33
-----------------------------------	--------



Door FL, Dent(s), Spot repair	148,33
-------------------------------	--------



Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00
---	------



Boot lid covering R, Scratch(es), Acceptable	0,00
--	------



Bumper R, Scratch(es), Repair and paint (complete)

355,89



Tailgate / Boot, Scratch(es), Acceptable

0,00



Wing trim FR, Scratch(es), Repair and paint (complete)

161,81



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03



Door FR, Bad repair, Repair and paint (complete)

534,95



Sill trim R, Scratch(es), Repair and paint (complete)

521,77



Door trim FR, Scratch(es), Spot repair

148,33



Door trim RR, Scratch(es), Spot repair

148,33



Door RR, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Acceptable

0,00



Roof, Dent(s), Paintless dent repair

95,47

