



PEUGEOT Boxer: 6236-MDW

Vinnumber:	VF3YCBPFB12W60384	Versionname:	335 L2 H2 BHD1 103kW (140CV) S&S 6 V. M furgón
First Registrationdate:	13/02/2023	Fiscalpower:	103kW 4P manual
Expertise Mileage:	243803	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	2	Radio:	
Number keys remote:	1	Central consol F:	
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

215/70/15/107 S				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/70 R 15 107 S
Tyre size FR				215/70 R 15 107 S
Tyre size RL				215/70 R 15 107 S
Tyre size RR				215/70 R 15 107 S
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Partition wall, Dent(s), Repair and paint (complete)



Seat cover FL, Burned, Replace



Registration document, Missing, Repair/replace (lump sum)



Seat cover FR, Burned, Replace



Outside rear-view mirror housing L, Crack, Repair and paint (complete)



Wing FL, Dent(s), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Door seal FL, Tear, Replace



Bumper F, Scratch(es), Paint



Wing FR, Dent(s), Repair and paint (complete)



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining L, Crack, Replace



Internal boot lining R, Crack, Replace



Bumper R, Dent(s), Repair and paint (complete)



Tyres, No damage, Check

