



**Peugeot 208: L197KK**

Vinnnumber:	<b>VR3UHZKXZMT059907</b>	Versionname:	<b>e-208 50kWh 100kW Allure Pack automaat</b>
First Registrationdate:	<b>21/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>87584</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Blanc Nacre metaallak</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>1175</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Lining semi-leather
GPS		Rear parking sensors
Autom climate control		
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Aluminium	4,8 mm	Bridgestone	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	4,8 mm	Bridgestone	Summer
Rear	Left	195 / 55 / 16 / 87 / H / Aluminium	4,2 mm	Bridgestone	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	5,0 mm	Bridgestone	Summer

**Assistance equipment**

Number of charging cables (rapid charge)	<b>1</b>
--	----------

Outside rear-view mirror housing L, Scratch(es), Polish



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (partial)



Bumper R, Scratch(es), Repair and paint (complete)



<b>Kenteken</b>	L197KK
<b>Merk Model</b>	Peugeot e-208 50kWh 100kW Allure Pack automaat
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	21-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
05-03-26	72.578	Onderhoudsbeurt
05-03-26	72.578	Uitlijnen voor en achterwielen
05-03-26	72.578	Vervanging band
11-09-25	53.157	Uitlijnen voor en achterwielen
19-06-25	39.056	APK
19-06-25	39.056	Ruitenwischerblad(en) voorzijde
19-06-25	39.056	Stellantis eerste EV controle
27-11-23	26.539	Onderhoudsbeurt
27-11-23	26.539	Remvloeistof
20-10-22	12.558	Onderhoudsbeurt
20-10-22	12.558	Reparatie band(en)