Audi

AUDI Q2 (GAG)(08.2020->) 30 TFSI BASE MOTEUR 1,0 LITRE(S) - 81 KW TFSI 4 PORTES

VIN: WAUZZZGA4PA006238



Description

Registration number 2CPG322	**Registration date** 05/10/2022	**Odometer** 72508 km
Color Bleu Navarre Métallisé	**Year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 999	**Gearbox type** Manual	**Engine type** Combustion
Fuel Type Petrol	**Number of gears** 6	**Drivetrain** Front Wheel Drive (FWD)
Max power 81 KW		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

interior equipment decorative trim inserts diamond paint Silver gray	standard seats front	4 speaker(s)
airbag driver side/passenger side	airbag passenger side deactivatable	sidebag front
immobilizer (electronic)	head rests rear (3-fold)	Audi connect (Remote / Control)
Audi connect (Emergency and Assistance System)	Audi music interface	battery 59 Ah
roof spoiler	transmission 6-speed	body: 4-door
standard suspension	radio-remote key	Electronic Stability Control (ESP)
tire pressure control system	progressive steering	brake discs rear (272 mm x 10 mm)
Disques de frein AV (288 mm x 25 mm)	rear seat backrest split/folding	light and rain sensor
electronic stability control (ESC)	wheelbase 2601 mm	Longlife-Service
turn signal lights LED in exterior mirror integrated	gasoline particulate filter (GPF)	refrigerant R 1234 YF
parking brake electromechanical	windshield washer jets heated	universal interface Bluetooth
tire repair kit	vehicle speed limiter	Type of drive: front-wheel drive
Moteur 1,0 litre(s) - 81 kW TFSI Catalyseur (DLAA)	multi-media Interface MMI basic plus / MMI radio plus	low emissions according to emission standard Euro 6d
windshield with sun-visor strip top	bumper variant: base	headlight LED
model refinement	exterior mirror vehicle colour	Sideblade vehicle-coloured
seat front left height-adjustable	Isofix mounts for child seat	floor mats velours
head airbag system (Sideguard)	antilock braking system (ABS)	driver assistance system: brake assistant (Audi pre sense front)
start/stop system	central locking system	daytime running lights

Optional

center armrest front comfort equipment	parking aid front and rear, optical (APS Plus)	generator 140 A
lumbar support front, electrically adjustable	Audi connect (web-based services)	Audi Smartphone Interface
rear lid open+close automatic (Hands-Free-Access system)	reversing camera	front camera (multi-functional camera windshield)
comfort automatic air-conditioning 2-zone	instrument cluster digital (virtual cockpit)	trailer coupling (removable ball head)
colour display (8,3 inch)	interior equipment aluminium look	rear lights LED
flooring: vinyl in cargo space/passenger compartment	light alloy rims 6,5x16 (5-spoke)	headlight washer system (headlight washer system)
multi-media Interface MMI Navigation Plus with MMI Touch	Assistance package parking	driver assistance system: start-up assistant (hold-assist)
comfort package	exterior mirror electrically adjustable, heated + folding, with automatic dimming and automatic curb-view tilting	lumbar support seat front left and right
interior mirror with automatic dimming	Interior package: standard seats, seat cover imitation leather / leather, black	seat covers/upholstery: imitation leather / leather
ambient lighting	navigation package	Driver Information System (DIS) (FIS) with colour display
safety package	driver assistance system: lane-change assist (Side Assist)	driver assistance system: passenger protection system (Audi pre sense basic)
driver assistance system: intersection assistant	metallic paintwork	scuff rails (aluminium) illuminated
cruise control (cruise control)	exterior mirror aspherical, left	exterior mirror convex, right
seat front right height-adjustable	seat heating front	driver assistance system: lane-departure warning
panoramic pop-up roof electric	glazing rear darkened (Privacy Glass)	steering wheel (leather - 3-spokes) with multiple function plus

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	14/10/2026	15/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Door / Back Left	Scratched	Acceptable
			
002	Wing / Back Left	Dent	Acceptable
			

Loose Items

- ☑ Hook /Hicth ball
- ☑ Triangle
- ☑ Rear parcel shelf
- ☑ Spare Key
- ☑ Tyre repair kit complete
- ☑ First aid kit
- ☑ Conformity certificate
- ☑ Safety vest
- ☑ Document holder
- ☑ Registration certificate owner
- ☑ Registration certificate

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	CONTINENTAL	215/60/16 Summer	3 mm
Front Right	CONTINENTAL	215/60/16 Summer	3 mm
Back Left	CONTINENTAL	215/60/16 Summer	6 mm
Back Right	CONTINENTAL	215/60/16 Summer	6 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.


Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right



Odometer


Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Other



Door / Back Left / Scratched



Wing / Back Left / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.