



Mercedes CL

Vinnumber:	W1K1186861N305186	Versionname:	
First Registrationdate:	16/05/2022	Fiscalpower:	
Expertise Mileage:	126954	Power Kw:	118
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1311
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Maintenance:	A9 over 3489km		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control:		Panoramic roof	
Steering wheel multifunctional:		Luggage cover	
Seats F heated:		Front parking sensors	
Radio multimedia:		Rear parking sensors	
Type of headlighting:	Headlighting LED	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

205/55/17/95 V				
Summer tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Tyre profile depth FL	4.0
Tyre profile depth FR	4.0
Tyre profile depth RL	5.0
Tyre profile depth RR	5.0
Tyre size FL	205/55 R 17 95 V
Tyre size FR	205/55 R 17 95 V
Tyre size RL	205/55 R 17 91 V
Tyre size RR	205/55 R 17 91 V
Tyre type FL	All seasons
Tyre type FR	All Seasons
Tyre type RL	Summer
Tyre type RR	Summer
Tyre make FL	2477
Tyre make FR	2480
Tyre make RL	261
Tyre make RR	261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Total cost ex VAT	2768,13
-------------------	----------------

Steering wheel, Worn, Acceptable	0,00
----------------------------------	-------------



Interior covering A pillar L, Tear, Acceptable 0,00



Interior covering A pillar L, Scratch(es), Acceptable 0,00



Backrest cover FL, Scratch(es), Acceptable 0,00



Interior covering A pillar R, Scratch(es), Acceptable 0,00



Interior covering A pillar R, Scratch(es), Acceptable 0,00



Registration document, Incomplete, Check 0,00



Windscreen, Repaired, Acceptable 0,00



Bumper F, Dent(s) and scratch(es), Replace and paint 1119,43



Grille, Dent(s), Replace 464,88



Alloy rim RL polished, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Central pillar L, Dent(s) and scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Acceptable 0,00



Boot carpet, Scratch(es), Acceptable 0,00



Tailgate / Boot, Dent(s), Acceptable

0,00



Rear light R tailgate, Broken, Replace

269,68



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

296,58



Bumper trim R, Scratch(es), Smart repair

116,69



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

204,21



Wing RR, Scratch(es), Spot repair

148,33



Central pillar R, Dent(s) and scratch(es), Spot repair

148,33

