



VOLKSWAGEN TIGUAN ALLSPACE: FN-185-VP

Vinnumber:	WVGZZZ5NZLM066786	Versionname:	VOLKSWAGEN TIGUAN ALLSPACE 2.0 TDI 190 DSG7 Carat 4Motion VP [5P] bva 7-190CH-10cv (SUV)
First Registrationdate:	18/02/2020	Fiscalpower:	
Expertise Mileage:	133347	Power Kw:	140
Bodytype:	SUV	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
GPS storage		Sun Roof electric	
GPS storage	SD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Headlight sprinkler	
Steering wheel leather		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of climate control	Autom climate control	Roof bar black	
		Rear view camera	
		Seat cover lining	Lining Other
			Lining Alcantara

Tyres

235/55/18/100 V				
Summer tyres:	Fr.L.	Continental: 75%	Fr.R.	Continental: 75%
	Re.L.	Continental: 55%	Re.R.	Continental: 55%
Tyre profile depth FL				3.5
Tyre profile depth FR				3.4
Tyre profile depth RL				4.7
Tyre profile depth RR				4.5
Tyre size FL				235/55 R 18 100 V
Tyre size FR				235/55 R 18 100 V
Tyre size RL				235/55 R 18 100 V
Tyre size RR				235/55 R 18 100 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Roof liner, Stain, Cleaning



Backrest cover FR, Stain, Cleaning



Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Bumper spoiler F, Scratch(es), Paint



Door FR, Dent(s), Acceptable



Door RR, Dent(s), Acceptable



Historique Maintenance

Immatriculation: **FN-185-VP**Date de 1ère immatriculation: **18/02/2020**Modèle: **Volkswagen TIGUAN ALLSPACE 2.0 TDI 190 DSG7 Carat 4Motion VP [5P] bva 7-190CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
09/03/2026	127.820	CONTROLE TECHNIQUE AUTO DOURDANNAIS	CONTROLE TECHNIQUE
15/09/2025	116.231	VIDALAUTOS	DURITE DE TURBO RPLT
21/08/2025	115.588	VIDALAUTOS	GRAISSAGE TOIT OUVRANT CTRL
	0		HUILE BV RPLT
	0		REVISION ET CLIM
	0		LIQUIDE LAVE GLACE
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
19/02/2025	103.370	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
25/07/2024	89.991	VIDALAUTOS	FILTRE A AIR RPLT
	0		REVISION
	0		REVISION
18/04/2024	83.100	VIDALAUTOS	DIVERS MOTEUR
	0		REVISION
	0		DIAG
	0		APPOINT D HUILE
09/02/2024	79.238	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
20/04/2023	60.473	VIDALAUTOS	DISQUES PLAQUETTES AR RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		ADBLUE
	0		LIQUIDE DE FREIN
	0		HUILE BV RPLT
	0		HUILE BV RPLT
	0		BALAIS ESSUIE GLACE AV AR
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM
07/12/2022	51.210	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS ETE
30/11/2021	30.426	GARAGE BAUBION	PILE DE CLE RPLT
	0		ADBLUE
	0		PILE DE CLE RPLT

Historique Maintenance

Immatriculation: **FN-185-VP**

Date de 1ère immatriculation: **18/02/2020**

Modèle: **Volkswagen TIGUAN ALLSPACE 2.0 TDI 190 DSG7 Carat 4Motion VP [5P] bva 7-190CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
	0		REVISION
08/07/2020	1.143	GARAGE BAUBION	DURITE D EAU RPLT