Renault Master 145PK Closed box Taillift Bakwagen LED Airco Cruise Camera Euro6 Meubelbak Koffer

VF6VG000370057135 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	vf6vg000370057135
First Registration	1/11/2023
Country of Origin	Germany
Mileage	176,002 km
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	Vehicle location:Veghel, NetherlandsCalculate delivery time and price
Vehicle location	Veghel, Netherlands
Amount of Axles	2
Type of suspension axle 2	parabolic
Tyre condition Axle 1 Left (MM)	9 mm
Tyre condition Axle 1 Right (M...	9 mm
Tyre condition Axle 2 Left (MM)	7 mm
Tyre condition Axle 2 Right (M...	7 mm
Tyre size Axle 1	225/65 R16
Tyre Size Axle 2	225/65 R16
Undercarriage	Wheeled
Wheelbase	433 cm
Engine Output HP/PK	145 hp
Cilinder Amount	4
Distribution type	Chain
Engine displacement (cc)	2299

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Engine Type	M9T
Power type	Diesel
Emission norm	Euro 6
Mileage	176002 km
Airco option	airco
Number of seats	3
Type of cabin	Single
Type of Radio	FM
Registration Date	2023-01-11
Empty weight	2760 kg
Towing weight	2500 kg
Tail lift brand	Dautel
Tail lift build year	2022
Tail lift capacity	750 kg
Plateau length	160 cm
Tail lift type	DFL 750
Transmission	Manual
Amount of forward gears	6
VIN / Serial Number/ Chassisn...	VF6VG000370057135
Brand	Renault
Model	Master
Product Group (Tax)	Closed Box
Type extended	Master 145PK
Axle capacity 1	1850 kg
Axle configuration	2002-10-04
Colour	white
Country of origin	DE
Gross Vehicle Weight (GVW)	3500 kg
Type of drive	FWD
Rear view camera	Rear view
Door opening height	228 cm
Door opening width	219 cm
Inner height	228 cm
Inner length	423 cm
Inner width	222 cm
Material floor	Wood
Superstructure brand	Humbaur
Superstructure build year	2021
Type of rear door	Tailgate
Type Lights	Halogen
Max load capacity	740 kg

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Vehicle Height (cm)	325 cm
Vehicle Length (cm)	695 cm
Vehicle Width (cm)	230 cm
Truck ID	70319467
Lot	16
First registration	January 11, 2023
November 3, 2026 at 02	07 PM

Damage & Condition

All known damages are listed and shown in photos for full transparency.

2 damages reported | Worst: Moderate



Multiple — Moderate
Cosmetic Damage
Other defects



Windshield — Minor
Cosmetic Damage
Condition windshield




Front / Right



Back / Left


FM1
VERONICA


BROWSE
Bluetooth
MP3
1RPT
2MIX
3
4
5
6A2
TEXT
FM1
VERONICA
RADIO
MEDIA
SETUP
TEL
ECO


HUMBAUR
MENU
CH1
CH2
CH3


ECO
A/C










x1000
0
1
2
3
4
5
6
7
18°c
176013km
536.4km
km/h
10
30
50
70
90
110
130
150
170
190
210


K9
RENAULT TRUCKS MASTER
FAHRERHANDBUCH
Radio Connect R&Go
RENAULT






R
O


AUTO
SOURCE
AUDIO
TEL
OK








By RENAULT TRUCKS








10


















DAUTEL




FM1
VERONICA
RADIO
MEDIA
SETUP
TEL




ECO


x1000
0
1
2
3
4
5
6
7
10
30
50
70
90
110
130
150
170
190
210
km/h













