MACADAM








HYUNDAI Tucson: 9327-MSW

Vinnumber:	**TMAJC812DPJ225671**	Versionname:	**1.6 TGDI PHEV 195kW Maxx Auto 4X4 todoterreno 195kW 5P automática**
First Registrationdate:	**10/07/2024**	Fiscalpower:	
Expertise Mileage:	**116658**	Power Kw:	
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Hybrid**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Tow bar	
Number keys remote	**2**	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**235/50/19/103 W**			
	Fr.L.	**Cooper: 5 mm**	Fr.R.	**Cooper: 5 mm**
	Re.L.	**Cooper: 5 mm**	Re.R.	**Cooper: 6 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**235/50 R 19 103 W**
Tyre size FR	**235/50 R 19 103 W**
Tyre size RL	**235/50 R 19 103 W**
Tyre size RR	**235/50 R 19 103 W**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**1957075**
Tyre make FR	**1957075**
Tyre make RL	**1957075**
Tyre make RR	**1957075**

Assistance equipment

Repair kit	**Yes**

Wing trim FL, Deformed / Strained, Replace



Wing FL, Dent(s), Repair and paint (complete)



Door FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Door trim RL, Deformed / Strained, Replace



Wing trim RL, Scratch(es), Paint



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing RR, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Replace




Tyres, No damage, Check










ALPHABET

Datos del vehículo

Marca	HYUNDAI	Matrícula	9327-MSW
Modelo	Tucson	VIN	TMAJC812DPJ225671
Versión	1.6 TGDI PHEV 195kW Maxx Auto 4X4 todoterreno 195kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
30/12/2024	Rev. 20.000 kms	22966	MERONE MOTOR S.L.U.
24/04/2025	Aceite motor - - - ALP EURO, Filtro aceite - OEM, Filtro aire - OEM - Rec.Plat. EuroTaller, Filtro antipolen - BOSCH - Rec.Plat. EuroTaller, Rellenar niveles, Sustituir Aceite-filtro, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Rellenar niveles, Tasa de gestión de aceites usados, Verificar Diagnosis	39096	MERONE MOTOR S.L.U.
28/05/2025	Ecotasa - N2, Goodyear / 235/50R19 103W VEC 4SEASONS G3 XL FP, Sustitucion y kit de montaje	46602	NEUMÁTICOS SOLEDAD (ZARAGOZA)
05/09/2025	Aceite motor - - - ALP EURO, Filtro aceite - UFI - Nueva, Filtro aire - PURFLUX - Rec.Plat. EuroTaller, Filtro antipolen - PURFLUX - Rec.Plat. EuroTaller, Líquido lavaparabrisas, Sustituir Aceite-filtro, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	65635	Juan Manuel Román Ortega
12/09/2025	Aceite motor - - - ALP EURO, Filtro aceite - UFI - Nueva, Filtro aire - PURFLUX - Rec.Plat. EuroTaller, Filtro antipolen - PURFLUX - Rec.Plat. EuroTaller, Líquido lavaparabrisas, Sustituir Aceite-filtro, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	65635	Juan Manuel Román Ortega
04/12/2025	Aceite motor - Precio litro pactado, Anticongelante, Filtro aceite - BOSCH - Rec.Plat. EuroTaller - MAHLE - Nueva, Filtro antipolen - PURFLUX - Rec.Plat. EuroTaller, Líquido lavaparabrisas, Sustituir Aceite-filtro, Sustituir Anticongelante, Sustituir Filtro antipolen, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	81274	Juan Manuel Román Ortega
10/04/2026	Aceite motor - - - ALP EURO, Arandela / tapón cárter, Filtro aceite - UFI - Nueva, Importe de pago por uso, Rellenar niveles, Serv inspección 105000 KM, Sustituir Rellenar niveles, Tasa de gestión de aceites usados, Verificar Diagnosis y borrado de averias después de reparar	102548	MERONE MOTOR S.L.U.

Fecha	Descripción	Kilómetros	Taller
01/06/2026	Alineado sencillo, Ecotasa - N2, Goodyear / 235/50R19 103W VEC 4SEASONS G3 XL FP, Sustitucion y kit de montaje	110781	NEUMÁTICOS SOLEDAD (ZARAGOZA)