

2-EWJ-828


2-EWJ-828 · TS 1.8 Hybrid Dynamic + Business pack · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EWJ-828	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	SB1ZB3AE10E094989
Model	Corolla Touring Sports	Cylinder Capacity	1.798 ^{cm3}
Model Versions	TS 1.8 Hybrid Dynamic + Business pack	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	19-02-2024
Color	Brown	Odometer	88.875 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	72	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 20-04-2026

Last maintenance odometer 81.358

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 mm	Semperit	205 mm	55 mm	16 inch	All Season
Rear Left	4 mm	Continental	205 mm	55 mm	16 inch	Summer
Front Right	1 mm	Semperit	205 mm	55 mm	16 inch	All Season
Rear Right	4 mm	Continental	205 mm	55 mm	16 inch	Summer
Spare Tire Type	None					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor - Right	Small scratch(es)	Bekleding	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Right	small dents / small scratches	Restyle / Touch-up	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	Small scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Acceptable
Roof	Dent(s)	



Damage Part

Hood



Damage Type

Dent(s)



Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Interior



Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Tyre - LR



Damage Type

Damaged

Repair Type

Replace


Acceptable

No



Damage Part

Alloy - Left Rear



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part
Fender - Rear Left



Damage Type
Small dent(s)



Repair Type
Restyle

Acceptable
No



Damage Part
Bumper - Rear



Damage Type
Scratch(es)



Repair Type
Spray

Acceptable
No



Damage Part
spoiler RB



Damage Type
Broken

Notes
Sierstrip

Repair Type
Replace

Acceptable
No