MACADAM









A3 1: 1WGS313

Vinnumber:	**WAUZZZ8V3KA090532**	Versionname:	
First Registrationdate:	**3/06/2019**	Fiscalpower:	
Expertise Mileage:	**132755**	Power Kw:	**85**
Bodytype:	**Hatchback**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:	**Front**		
Fueltype:	**Petrol**		
Maintenance	**NOT OK**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	**No Tow bar**
Board Computer			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of headlighting	**Headlighting Xenon**		
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining fabrics**		
Type of climate control	**Autom climate control**		
Type of radio	**Multimedia CD**		
Type of GPS storage	**SD present**		

Tyres

Summer tyres:	**205/55/16/91 V**			
	Fr.L.	**Michelin: 6 mm**	Fr.R.	**Michelin: 6 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/55 R 16 91 V**
Tyre size FR	**205/55 R 16 91 V**
Tyre size RL	**205/55 R 16 91 V**
Tyre size RR	**205/55 R 16 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**	Jack	**Yes**
Number of charging cables (rapid charge)	**0**		

Total cost ex VAT	**1127,05**
Interior covering A pillar L, Burned, Replace	**77,02**





Interior, Smell, Ozone treatment	**300,00**



Seat cover FR, Stain, Cleaning	**32,07**




Service, Maintenance, Execute	**0,00**



Bumper moulding F, Broken, Replace	**15,84**




Windscreen, Stone chip(s), Acceptable	**0,00**




Bonnet, Dent(s), Acceptable	**0,00**




Headlight R, Scratch(es), Acceptable	**0,00**




Bumper F, Scratch(es), Acceptable	**0,00**




Door RL, Dent(s), Paintless dent repair	**69,30**





Boot lid covering R, Scratch(es), Smart repair	**121,70**




Bumper R, Scratch(es), Acceptable	**0,00**







Alloy rim FR, Scratch(es), Repair and paint (complete)	**161,12**






Roof, Dent(s), Acceptable	**0,00**






Bodywork, Not original part, Sticker removal	**350,00**



