



Mercedes A-Klasse (UKL): 2ASU131

Vinnumber:	W1K1771861J320436	Versionname:	A250e Limousine Business Solution 1.3i 218pk/cv
First Registrationdate:	2/07/2021	Fiscalpower:	4p 8G-DCT
Expertise Mileage:	149457	Power Kw:	118
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Maintenance	ass B4 plus 6904 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	Tow bar collapsible
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/45/18/95 Y				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.0
Tyre size FL				225/45 R 18 95 Y
Tyre size FR				225/45 R 18 95 Y
Tyre size RL				225/45 R 18 91 W
Tyre size RR				225/45 R 18 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Centre console, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Tailgate / Boot, Repaired, Check



Bumper R, Scratch(es), Acceptable



Rear light L, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Outer sill R, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2ASU131
Merk Model	Mercedes A250e Limousine Business Solution 1.3i 218pk/cv 4p 8G-DCT
Brandstofsoort	Benzine
Datum deel1	7/2/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/28/26	148,770	vergrendelingsmotor (deur, koffer, tank	Vervangen
12/5/25	131,361	klein materiaal	
12/5/25	131,361	mercedes assyst a	Uitvoeren
12/5/25	131,361	remvloeistof	Vervangen
12/5/25	131,361	versnellingsbakolie	Vervangen
2/20/25	105,642	klein materiaal	
2/20/25	105,642	mercedes assyst b	Uitvoeren
2/20/25	105,642	ruitenswisserrubber vooraan	Vervangen
2/20/25	105,642	schuif/ -kanteldak	Smeren
2/20/25	105,642	trekhaak	Reinigen
4/11/24	79,468	bougie	Vervangen
4/11/24	79,468	klein materiaal	Uitvoeren
4/11/24	79,468	luchtfILTER	Vervangen
4/11/24	79,468	mercedes assyst a	Uitvoeren
1/26/24	72,965	ruitenswisserrubber vooraan	Vervangen
5/22/23	51,562	klein materiaal	
5/22/23	51,562	mercedes assyst b	Uitvoeren
5/22/23	51,562	remvloeistof	Vervangen
5/22/23	51,562	ruitenswisserrubber vooraan	Vervangen
5/22/23	51,562	schuif/ -kanteldak	Smeren
5/22/23	51,562	trekhaak	Controleren
10/21/22	32,399	klein materiaal	Uitvoeren
10/21/22	32,399	ruitenswisserrubber vooraan	Vervangen
8/9/22	23,953	klein materiaal	Uitvoeren
8/9/22	23,953	mercedes assyst a	Uitvoeren
3/2/22	12,077	controle niveaus	Uitvoeren