MACADAM







BMW X1 (UKL): 2CEN338

Vinnumber:	**WBA71AB0905V55088**	Versionname:	**X1 (F48) 25e xDrive 1.5i 220pk/cv 5p Aut.**
First Registrationdate:	**24/06/2022**	Fiscalpower:	
Expertise Mileage:	**183863**	Power Kw:	**92**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**2000.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/55/17/97 W**			
	Fr.L.	**Continental: 6 mm**	Fr.R.	**Continental: 6 mm**
	Re.L.	**Continental: 6 mm**	Re.R.	**Continental: 6 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**225/55 R 17 97 W**
Tyre size FR	**225/55 R 17 97 W**
Tyre size RL	**225/55 R 17 97 W**
Tyre size RR	**225/55 R 17 97 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Roof liner, Dirty, Cleaning





Seat cover FL, Worn, Acceptable



Door panel FL, Worn, Acceptable



Backrest cover RL, Dirty, Cleaning



Door panel FL, Dirty, Cleaning



Bumper spoiler F, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Door seal FL, Deformed / Strained, Acceptable



Alloy rim FL, Scratch(es), Acceptable



Door FL, Scratch(es), Spot repair



Boot lid covering R, Dirty, Cleaning






Wing RR, Repaired, Check




Door FR, Repaired, Check




Wing RR, Scratch(es), Acceptable




Step R, Scratch(es), Acceptable




Door RR, Repaired, Check




Wing RR, Dent(s), Paintless dent repair




Side window trim RR, Scratch(es), Acceptable




Side window trim FR, Scratch(es), Acceptable




Bodywork, Paint measurement, Check



Onderhoudshistorie van: WBA71AB0905V55088

ALPHABET

Kenteken	2CEN338
Merk Model	BMW X1 (F48) 25e xDrive 1.5i 220pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	6/24/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/3/26	152,201	batterij	Vervangen
2/3/26	152,201	BMW/MINI service standaard omvang	Uitvoeren
2/3/26	152,201	BMW/MINI service voertuig-check	Uitvoeren
2/3/26	152,201	bougie	Vervangen
2/3/26	152,201	klein materiaal	
2/3/26	152,201	koelwatervloeistof	Bijvullen/-laden
2/3/26	152,201	remblokken achter	Vervangen
2/3/26	152,201	remblokken vooraan	Vervangen
2/3/26	152,201	ruitenwisservloeistof	Bijvullen/-laden
2/3/26	152,201	service luchtfilter	Uitvoeren
2/3/26	152,201	service microfilter	Uitvoeren
2/3/26	152,201	service motorolie	Uitvoeren
3/25/25	114,985	batterij	Vervangen
3/25/25	114,985	BMW/MINI service standaard omvang	Uitvoeren
3/25/25	114,985	klein materiaal	
3/25/25	114,985	remvloeistof	Vervangen
3/25/25	114,985	ruitenwisserrubber achter	Vervangen
3/25/25	114,985	ruitenwisserrubber vooraan	Vervangen
3/25/25	114,985	service microfilter	Uitvoeren
3/25/25	114,985	service motorolie	Uitvoeren
9/10/24	83,199	BMW/MINI service standaard omvang	Uitvoeren
9/10/24	83,199	BMW/MINI service voertuig-check	Uitvoeren
9/10/24	83,199	bougie	Vervangen
9/10/24	83,199	klein materiaal	Uitvoeren
9/10/24	83,199	service luchtfilter	Uitvoeren
9/10/24	83,199	service microfilter	Uitvoeren
9/10/24	83,199	service motorolie	Uitvoeren
7/3/24	68,276	controle niveaus	Uitvoeren
12/5/23	39,041	BMW/MINI service standaard omvang	Uitvoeren
12/5/23	39,041	klein materiaal	Uitvoeren
12/5/23	39,041	ruitenwisserrubber achter	Vervangen
12/5/23	39,041	ruitenwisserrubber vooraan	Vervangen
12/5/23	39,041	service microfilter	Uitvoeren
12/5/23	39,041	service motorolie	Uitvoeren