

Mercedes

MERCEDES-BENZ A BERLINE (BM 177)(08.2018->) A 180 D (177.103) MOTEUR 1,5 LITRE(S) - 85 KW CDI CATALYSEUR 4 PORTES

VIN: W1K1771031J213738



Description

Registration number	Registration date	Odometer
	06/03/2020	94334 km
Color	Year	Upholstery
MOUNTAINGRAU - MET.	2018	-
Number of doors	Number of seats	Generation
4	5	-
Engine displacement	Gearbox type	Engine type
1461	Automatic	Combustion
Fuel Type	Number of gears	Drivetrain
Diesel	7	Front Wheel Drive (FWD)
Max power		
85 KW		

Vehicle Equipments

Standard

Light and Vision package	sun visors with mirror (illuminated)	airbag driver side/passenger side
airbag passenger side deactivatable	lap airbag front (Pelvisbag)	kneebag driver side
sidebag front	rain/light sensor	body: 4-door
automatic air-conditioning system (Thermatic)	vehicle setup (online services / Apps)	USB connection in rear seat area
Electronic Stability Control (ESP)	tire pressure control system	windshield wiper with rain sensor
diesel particulate filter	Keyless Go starting system	window lifter electric front + rear
Mercedes-Benz emergency call system	communication module (LTE) preparation Mercedes me connect	engine 1,5 liter - 85 kW CDI catalyst
tire 205/60 R16 ..W	cruise control (cruise control)	exterior mirror electrically adjustable and heated, both
vehicle monitoring (vehicle tracking system)	head airbag system (Sideguard)	antilock braking system (ABS)
driver assistance system: active brake assistant	driver assistance system: active lane-keeping assistant	driver assistance system: Multi-Sense (driving mode switch)
driver assistance system: speed limit display	multimedia system MBUX (digital multimedia system)	start/stop system
rear axle: torsion beam	steering wheel (Sport) with multiple function	daytime running lights LED

Optional

alarm system for seat belts rear	année de modification avec Code 050 (09/2)	année de modification avec Code 800
antenna for telephone (GPS)	lumbar support seat front left and right, electrically adjustable	transmission 7-speed - dual-clutch transmission S-tronic
multi-functional camera	active hood	voice-command system extended functions (MBUX)
center console front with roll-up cover / tray	Design and equipment line Style	side skirt vehicle colour
radiator grille diamond optic	roof liner cloth	seat covers/upholstery: cloth / leather look
comfort seats front	beverage holder front (dual)	Diesel - exhaust treatment Bluetec SCR Generation 3
instrument cluster digital (virtual cockpit)	direct steering with variable steering assistance	rear seat backrest split/folding
fire extinguisher	refrigerant R 1234 YF	roof liner black
light alloy rims 6,5x16 (mesh-type rim)	light alloy rims	tire repair kit
media display	moteur 4 cyl. en ligne diesel OM 608	Parking package
driver assistance system: parking assistant (Active Park Assist)	reversing camera	mirror package
exterior mirror electrically folding	side/rear-view mirrors with automatic dimming	Seat Comfort package
metallic paintwork	headlight LED High Performance	preparation car sharing
preparation digital radio	exterior mirror with blind-spot assistant	interior mirror and exterior mirror left with automatic dimming
seat heating front	Smartphone integrated	Isofix mounts for child seat at rear seat
floor mats velours	comfort suspension lowered (Agility Control)	driver assistance system: traffic information system Live traffic
navigation system: hard disk navigation	panoramic sliding roof	Touchpad (center console)
steering wheel (leather)	steering wheel with shift rockers/buttons	radiator grille, active air doors

Active warning lights

Maintenance indicator

Statement details



Statement date
16/07/2026

Inspection approval date
17/07/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	Non Compliant	Cleaning
			
002	Maintenance indicator	Missing	Carry out
			
003	Bumper / Back	Scratched	Polishing
			
004	Rim / Front Right Rim/Tyre diameter : 16 "	Scratched	Acceptable
			
005	Bumper / Front	Scratched	Acceptable



006	Windscreen / -	Scratched	Replace
			
007	Lower bumper / Back	Scratched	Acceptable
			

Loose Items

☐ Toolkit	☐ Slow charging cable (Type 2, Mode 2)	☐ Quick charging cable (Type 2, Mode 3)
☐ Load cover	☐ Service book	☐ Warranty booklet
☒ Conformity certificate	☒ Registration certificate	☒ Registration certificate owner
☐ Locking wheel nut	☒ Card key	☐ Locking wheel nuts key
☐ Remote key	☒ Compressor tyre repair kit	☐ Jack
☐ Towing hook	☐ Hook /Hiich ball	☒ Spare Key
☐ Cargo net	☐ Safety vest	☐ Tyre repair kit complete
☐ Security Kit	☐ Jack handle crank	☒ User manual
☐ Satellite navigation	☐ In-car tools	☐ Rear parcel shelf
☒ Document holder	☐ Refill tyre repair kit	☐ Spare wheel tyre
☐ Charging cable bag	☐ Remote control	☐ Triangle
☐ First aid kit		

Main set of tyres

Front Left	PIRELLI	205 / 60 / 16 / Summer	7 mm
Front Right	PIRELLI	205 / 60 / 16 / Summer	7 mm
Back Left	PIRELLI	205 / 60 / 16 / Summer	8 mm
Back Right	PIRELLI	205 / 60 / 16 / Summer	8 mm

Comments

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right




Odometer



Navigation




Spare Tyre




Vin



Other



Other



Other



Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Maintenance indicator / Missing



Maintenance indicator / Missing



Bumper / Back / Scratched



Bumper / Back / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Bumper / Front / Scratched



Windscreen / - / Scratched



Windscreen / - / Scratched



Lower bumper / Back / Scratched

