


Vehicle details

VIN	WVGZZZE2Z MP036586	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.4 77kWh Life Auto 5d	Maintenance mileage	-
Registration date	01/06/2021	Year	2021	Exterior Color	Unknown
Odometer	121 789 km	Engine size	-	Interior Color	Unknown
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date 08/07/2026



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Wireless charger	✗
Rear parcel shelf	✓
Vehicle charger	✓

Technical Document

User manual	✓
Spare key	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 255/55/19 Summer 5.0 mm



Pirelli 255/55/19 Summer 5.0 mm



Pirelli 255/55/19 Summer 6.0 mm

Pirelli 255/55/19 Summer 6.0 mm


Exterior

3



Part	Bumper
Position	Front
Damages	Dent & Chips
Severity	-
Repair mode	Repair

5



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

6



Part	Step plate
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

7



Part	Step plate
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

8



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

10



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

12



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair


Interior damage

2



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

11



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

1		Part	Wireless charger
		Position	-
		Damages	Missing
		Severity	-
		Repair mode	For info