MACADAM









MERCEDES-BENZ VITO MIXTO COMPACT: GH-518-KG

Vinnumber:	**W1V44770114129668**	Versionname:	**MERCEDES-BENZ VITO MIXTO COMPACT 110 CDI Mixto CP SELECT VU [4P] bvm 6-102CH-7cv (fourgon tÃ´lÃ©double cabine)**
First Registrationdate:	**6/07/2022**	Fiscalpower:	
Expertise Mileage:	**185175**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Sliding door right-side	
Seats F heated		Seat cover lining	**Lining Leather**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/55/17/107 T**			
	Fr.L.	**Uniroyal: 20%**	Fr.R.	**Uniroyal: 25%**
	Re.L.	**Continental: 50%**	Re.R.	**Continental: 55%**

Tyre profile depth FL	**6.9**
Tyre profile depth FR	**6.4**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.7**
Tyre size FL	**225/55 R 17 107 T**
Tyre size FR	**225/55 R 17 107 T**
Tyre size RL	**225/55 R 17 107 T**
Tyre size RR	**225/55 R 17 107 T**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**265**
Tyre make FR	**265**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Spare wheel	**No**	Jack	**Yes**

Armrest F M, Tear, Replace




Air vent, mid-dashboard, Broken, Replace




Air vent, mid-dashboard, Broken, Replace




Floor mat F, Tear, Replace





Alloy rim RL, Scratch(es), Acceptable





Wing FL, Dent(s), Repair and paint (complete)




Door FL, Dent(s) and scratch(es), Repair and paint (complete)






Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Paint






Side wall RR, Dent(s), Repair and paint (complete)





Door FR, Dent(s), Acceptable




Spare tyre, Missing, Replace



Spare rim, Missing, Replace



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Paint







ALPHABET

Historique Maintenance

Immatriculation: **GH-518-KG** Date de 1ère immatriculation: **06/07/2022**

Modèle: **Mercedes VITO MIXTO COMPACT 110 CDI Mixto CP SELECT VU [4P] bvm 6-102CH-7cv (fourgon tôlédouble cabine)**

Date	Kilométrage	Fournisseur	Descriptif
11/04/2025	154.895	SA VEHICULES INDUSTRIELS AVIGNONNAIS	LIQUIDE DE REFROIDISSEMENT RPLT
	0		DIVERS
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AR RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
11/04/2025	152.002	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
	0		REMPLACEMENT PNEUS ETE
16/11/2024	124.978	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER
25/10/2024	122.542	GORRIAS VEHICULES INDUSTRIELS	INJECTEUR ADBLUE RPLT
11/10/2024	120.169	DAIMLER TRUCK RETAIL PARIS	DIVERS MOTEUR
	0		TELECHARGEMENT CALCULATEUR
	0		DIVERS ECHAPPEMENT
07/05/2024	107.189	SA VEHICULES INDUSTRIELS AVIGNONNAIS	DISQUES PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE DE FREIN
	0		DIVERS ECHAPPEMENT
24/05/2023	69.271	NORAUTO SAS (PRODUIT SPE)	REFUS PNEU
	0		REMPLACEMENT PNEUS 4 SAISONS
24/05/2023	53.545	SA VEHICULES INDUSTRIELS AVIGNONNAIS	LIQUIDE LAVE GLACE
	0		REVISION
26/12/2022	23.241	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS HIVER
	0		GARDIENNAGE