



Cupra Born: P837TP

Vinnumber:	VSSZZK1ZNP005230	Versionname:	Sneller rijden Born 150kW/62kWh Copper Edition One Aut.
First Registrationdate:	29/06/2022	Fiscalpower:	
Expertise Mileage:	98012	Power Kw:	150
Bodytype:		Body colour	vapor grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	1084
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Panoramic roof
Radio multimedia		Rear parking sensors
		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 45 / 20 / 95 / T / Aluminium	5,5 mm	Continental	Summer
	Right	215 / 45 / 20 / 95 / T / Aluminium	5,2 mm	Continental	Summer
Rear	Left	215 / 45 / 20 / 95 / T / Aluminium	5,1 mm	Continental	Summer
	Right	215 / 45 / 20 / 95 / T / Aluminium	4,3 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Interior, Dirty, Cleaning



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Roof pillar L, Scratch(es), Polish



Sill trim L, Scratch(es), Repair and paint (complete)



Bumper F, Crack, Repair and paint (complete)



Bumper moulding F, Dent(s) and scratch(es), Replace and paint



Bumper spoiler F, Broken, Replace



Bumper moulding F, Scratch(es), Replace and paint



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Polish



Fuel cap cover, Scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace




Bumper R, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Replace



Rear light L, Scratch(es), Replace



Kenteken	P837TP
Merk Model	Cupra Sneller rijden Born 150kW/62kWh Copper Edition One Aut.
Brandstofsoort	Elektrisch
Datum deel1	29-06-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
08-05-25	0	Accu
16-05-23	35.859	Reparatie band(en)