



Opel Corsa: N125VT

Vinnumber:	VXKUH2KXZM4366027	Versionname:	Corsa-E 3 fase lader 100kW / 50kWh Edition
First Registrationdate:	29/12/2021	Fiscalpower:	
Expertise Mileage:	103087	Power Kw:	100
Bodytype:		Body colour	White Jade
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Electric	Parking lot	798
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2
Autom climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Steel	8,0 mm	Continental	All season
	Right	195 / 55 / 16 / 87 / H / Steel	7,2 mm	Continental	All season
Rear	Left	195 / 55 / 16 / 87 / H / Steel	8,1 mm	Continental	All season
	Right	195 / 55 / 16 / 87 / H / Steel	7,4 mm	Continental	All season

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Floor mat(s), Worn, Replace



Interior, Stain, Cleaning



Wing FL, Dent(s), Repair and paint (complete)





Door RL, Bad repair, Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Bodywork, Chemical polution, Polish



Roof, Hail damage, Paintless dent repair (hail)



Kenteken	N125VT
Merk Model	Opel Corsa-E 3 fase lader 100kW / 50kWh Edition
Brandstofsoort	Elektrisch
Datum deel1	29-12-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
29-05-26	100.210	Onderhoudsbeurt
29-05-26	100.210	Remvloeistof
28-11-25	87.419	APK
28-11-25	87.419	Vervanging band
28-09-25	0	Accu
14-03-25	69.892	Onderhoudsbeurt
14-03-25	69.892	Reparatie band(en)
14-03-25	69.892	Ruitenwisserblad(en) voorzijde
14-03-25	69.892	Sleutelbatterij
08-07-24	56.977	Airco pomp
08-07-24	56.977	Tractiebatterij lader
10-04-24	56.292	Onderhoudsbeurt
23-01-23	26.483	Onderhoudsbeurt
27-09-22	12.850	Onderhoudsbeurt