MACADAM







Skoda Kamiq (UKL): 2ELU109

Vinnumber:	**TMBGR6NW3P3189322**	Versionname:	**Kamiq Clever 1.0TSi 110pk/cv 5p DSG7**
First Registrationdate:	**15/11/2023**	Fiscalpower:	
Expertise Mileage:	**63229**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**plus 26000 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/17/95 V**			
	Fr.L.	**Vredestein: 4 mm**	Fr.R.	**Vredestein: 4 mm**
	Re.L.	**Vredestein: 5 mm**	Re.R.	**Vredestein: 5 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/55 R 17 95 V**
Tyre size FR	**205/55 R 17 95 V**
Tyre size RL	**205/55 R 17 95 V**
Tyre size RR	**205/55 R 17 95 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**2480**
Tyre make RR	**2480**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Bumper F, Scratch(es), Acceptable




Bonnet, Dent(s) and scratch(es), Repair and paint (complete)








Door FL, Dent(s) and scratch(es), Acceptable





Bumper R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Acceptable




Onderhoudshistorie van: TMBGR6NW3P3189322

ALPHABET

Kenteken	2ELU109
Merk Model	Skoda Kamiq Clever 1.0TSi 110pk/cv 5p DSG7
Brandstofsoort	Benzine
Datum deel1	11/15/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/2/26	59,857	batterij	Vervangen
7/2/26	59,857	bougie	Vervangen
7/2/26	59,857	Inspectie met olieververvanging (vast in	Uitvoeren
7/2/26	59,857	klein materiaal	
7/2/26	59,857	koelwatervloeistof	Bijvullen/-laden
7/2/26	59,857	luchtfilter interieur	Vervangen
7/2/26	59,857	remvloeistof	Vervangen
7/2/26	59,857	ruitenwisserrubber achter	Vervangen
7/2/26	59,857	ruitenwisserrubber vooraan	Vervangen
7/2/26	59,857	ruitenwisservloeistof	Bijvullen/-laden
4/4/25	24,897	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
4/4/25	24,897	ruitenwisserrubber achter	Vervangen
9/4/24	16,714	olie bijvullen	Bijvullen/-laden