


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number				Code / Agency				Date accident 23/06/2026							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 23/06/2026		Date first survey 24/06/2026		Place ZANICA		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) CUPRA FORMENTOR 2.0 TDI 4Drive DSG								Plate GN176HH		Vin Chassis VSSZZZKM8PR045869				First Registration 21/03/2023							
Usage status NON CONOSCIUTO		Km 31955		Tyres % 60		Color GRIGIO		Type of enamel METALLIZED/DOUBLE				Consistency of damage TO BE CHECKED		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif Time		Dif Time		Dif Time		Time				* (VAT excluded)			
1		5FF807217QGRU		Front bumper				M		M		M									
1		5FF807568B041		Rear bumper lower cladding				L		L		L									
1		5FF807434G9DG		Rear bumper				L		L		L									
1		Codice Ricambio		Ripristino con tecnica del levabolli																	
1		Codice Ricambio		Ripristino cerchio in lega ant.				R													
1		Codice Ricambio		Ripristino cerchio in lega post.				L													
1		Codice Ricambio		Seconda chiave																	
1		Codice Ricambio		Cerchio in lega ant. - PRM				L													
1		Codice Ricambio		Cerchio in lega post. - PRM				R													

New for old value (N)	Remarks Pneum. Continental 245/45 R18. Vhl sporco, grandinato.
-----------------------	--

ALPHABET

Telaio VSSZZZKM8PR045869

GN176HH

CUPRA FORMENTOR 2.0 TDI 4Drive DSG sports utility vehicle 150CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
7.312	07/08/24	Tagliando a 15 000 km	Tagliando a 15 000 km
12.378	23/01/25	Maintenance	Batteria
23.569	28/08/25	Tagliando a 20 000 km	Tagliando a 20 000 km
28.696	29/10/25	Maintenance	Generico
29.164	25/11/25	Maintenance	Generico
29.549	16/01/26	Maintenance	Generico