


2-FAJ-896 · Move! 1.0 TSI 110cv DSG unicolor · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAJ-896	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ2RR084983
Model	Arona	Cylinder Capacity	999 ^{cm3}
Model Versions	Move! 1.0 TSI 110cv DSG unicolor	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	06-03-2024
Body Type	5 door hatchback	Odometer	69.976 ^{Km}
Color	Black	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	81		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Vredestein	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	5 ^{mm}	Vredestein	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	5 ^{mm}	Vredestein	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	5 ^{mm}	Vredestein	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Burned	Vloerbedekking	Cloth Repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Damaged	Vloerbedekking	Cloth Repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Right	Small scratch(es)	Handgreep	Acceptable	Yes



Damage Part
Reardoor - Left

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
Bumper - Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Tailgate

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No