



**Volkswagen Up: H107SR**

Vinnnumber:	<b>WVWZZZAAZLD033623</b>	Versionname:	<b>Move-Up! 1.0 BMT 44kW</b>
First Registrationdate:	<b>7/05/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>39932</b>	Power Kw:	<b>44</b>
Bodytype:		Body colour:	<b>Dark Silver metallic</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Parking lot:	<b>1153</b>
Number of seats:	<b>4</b>		
Type of rims (mounted):	<b>Steel</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>1</b>
Manual climate control	
Radio multimedia	

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	175 / 65 / 14 / 86 / H / Steel	6,2 mm	Continental	All season
	Right	175 / 65 / 14 / 86 / H / Steel	6,8 mm	Continental	All season
Rear	Left	175 / 65 / 14 / 86 / H / Steel	5,5 mm	Continental	All season
	Right	175 / 65 / 14 / 86 / H / Steel	4,0 mm	Continental	All season

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Ignition key, Missing, Replace

No pictures to display

Interior, Dirty, Cleaning



Door FL, Dent(s), Repair and paint (complete)





Door RL, Dent(s), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Aerial, Missing, Replace



<b>Kenteken</b>	H107SR
<b>Merk Model</b>	Volkswagen Move-Up! 1.0 BMT 44kW
<b>Brandstofsoort</b>	Benzine
<b>Datum deel1</b>	07-05-20

Datum reparatie	Kilometerstand	Reparatie omschrijving
25-03-26	38.657	APK
25-03-26	38.657	Vervanging band
21-01-26	0	Accu
21-01-26	37.801	Accu
04-06-25	33.279	Onderhoudsbeurt
04-06-25	33.279	Remvloeistof
04-06-25	33.279	Ruitenwischerblad(en) voorzijde
18-09-24	0	Accu
18-09-24	27.448	Accu
11-09-24	0	Accu
17-06-24	27.436	Bougie
17-06-24	27.436	Luchtfilter
17-06-24	27.436	Onderhoudsbeurt
22-04-24	26.869	APK
10-07-23	17.858	Onderhoudsbeurt
10-07-23	17.858	Remvloeistof
10-07-23	17.858	Ruitenwischerblad(en) achterzijde
10-07-23	17.858	Ruitenwischerblad(en) voorzijde
04-07-22	8.903	Onderhoudsbeurt
15-03-22	5.335	Accu
04-05-21	4.303	Onderhoudsbeurt