MACADAM









Polestar 2: S676VK

Vinnumber:	**YSMVSEFE9PL150296**	Versionname:	**Polestar 2 170kW/ 69kWh Single Motor Standard Range**
First Registrationdate:	**26/04/2023**	Fiscalpower:	
Expertise Mileage:	**169903**	Power Kw:	**170**
Bodytype:		Body colour	**Magnesium (metallic)**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**649**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Rear view camera	
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / W / Aluminium	6,1 mm	Bridgestone	Winter
	Right	245 / 45 / 19 / 102 / W / Aluminium	5,1 mm	Bridgestone	Winter
Rear	Left	245 / 45 / 19 / 102 / V / Aluminium	6,0 mm	Pirelli	Winter
	Right	245 / 45 / 19 / 102 / V / Aluminium	6,0 mm	Pirelli	Winter

Assistance equipment

Number of charging cables (rapid charge)	**1**

Outer backrest protection R, Dirty, Chemical cleaning



Seat cover FL, Dirty, Chemical cleaning



Seat cover FR, Dirty, Chemical cleaning



Door RL, Scratch(es), Polish




Alloy rim RL, Deformed / Strained, Replace




Alloy rim FL, Scratch(es), Repair and paint (complete)



Bumper F, Stone chip(s), Repair and paint (complete)





Bonnet, Stone chip(s), Repair and paint (complete)




Door FR, Scratch(es), Polish




Boot lid covering R, Scratch(es), Replace



Tailgate / Boot, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)



Onderhoudshistorie van: YSMVSEFE9PL150296

ALPHABET

Kenteken	S676VK
Merk Model	Polestar Polestar 2 170kW/ 69kWh Single Motor Standard Range
Brandstofsoort	Elektrisch
Datum deel1	4/26/23

Datum reparatie	Kilometerstand	Reparatie omschrijving
3/27/26	144,684	Onderhoudsbeurt
3/27/26	144,684	Ruitenwisserblad(en) voorzijde
3/27/26	144,684	Sleutelbatterij
3/5/26	141,473	Boordcomputer
3/5/26	141,473	Elektrische achterklep
7/10/25	108,145	Onderhoudsbeurt
4/15/25	93,892	Onderhoudsbeurt
4/15/25	93,892	Ruitenwisserblad(en) voorzijde
1/10/25	70,000	Vervanging band
9/18/24	64,631	Onderhoudsbeurt
4/30/24	49,750	Elektromotor
6/19/23	9,110	Vervanging band
5/15/23	3,641	Reparatie band(en)