



FORD Mondeo: 7507-LVB

Vinnumber:	WF0DXXWPCMK07666	Versionname:	2.0 Híbrido 138kW (187CV) Trend HEV Auto sedán 138kW 4P automática
First Registrationdate:	29/11/2021	Fiscalpower:	
Expertise Mileage:	171694	Power Kw:	
Bodytype:	Berline	Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

215/60/16/95 V				
Summer tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/60 R 16 95 V
Tyre size FR				215/60 R 16 95 V
Tyre size RL				215/60 R 16 95 V
Tyre size RR				215/60 R 16 95 V
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes
Interior, Dirty, Cleaning	



Seat cover FL, Burned, Replace



Registration document, Missing, Repair/replace (lump sum)



Wing RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Mirror side repeater R, Broken, Replace



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check



