

Expertise

Protocol number: 45578328
Order No. / Reference: 26354469
Inspection date: 22 May 2026

Manufacturer: Seat

Model: Leon Sportstourer 2.0 TDI DSG Style

VIN: VSSZZKL0PR034372



Vehicle details

Manufacturer / Type / Model / Equipment

Seat Leon Sportstourer 2.0 TDI DSG Style

Vehicle Identification number VSSZZKL0PR034372

Mileage (Read) 58,316 km

First registration 27 Apr 2023

Number of holders 1

Power / Engine displacement 110 kw / 1,968 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Automatic / 7

Type of drive Front drive

Type of vehicle Station wagon

Colour / colour code Urban Silber Metallic

Doors / Seats 5 / 5

Upholstery type Alcantara / Leather

Colour of upholstery Black-Anthracite



Equipment

Standard equipment

- Storage compartment in the front doors
- Driver and passenger airbags
- Airbag: Head airbag system, front and rear
- Electrically adjustable and heated exterior mirrors
- LED turn signals integrated into the exterior mirrors
- On-board computer
- Roof rails, black
- Electronic differential lock XDS
- Electronic parking brake
- Electric window regulator with anti-pinch protection and one-touch function
- Luggage compartment lighting
- Speed limiter
- Transmission: 7-speed DSG
- Heated rear window
- ISOFIX child seat restraint system, triple in the 2nd row of seats
- Front headrests (2)
- Steering wheel: Three-spoke leather steering wheel with multifunction controls
- Rear center armrest with pass-through option
- Fog lights with cornering light function in LED technology
- Upholstery: Cloth
- Radio accessories: 6 speakers
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Wheels: Tyre fit
- SEAT CONNECT
- Seat belts: Three-point automatic front and rear
- Seats: Driver's seat with height adjustment
- Seats: Lumbar support for front passenger
- Seats: Lumbar support for driver
- Sun visor on driver and passenger side
- Lane departure warning system
- Power outlet: 12V socket in the trunk
- Front Assist area monitoring system with City Emergency Braking function
- Electronic immobilizer
- Storage pockets on the backs of the front seats
- Airbag: Passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Exterior mirror housings, bumpers and door handles in body color
- third brake light
- Diesel particulate filter
- Tachometer
- Electronic Stability Control (ESC) including Anti-lock Braking System (ABS)
- Gear recommendation display
- luggage compartment roller blind
- Cruise control system
- Illuminated glove compartment
- rear window wiper
- Keyless Go (engine start/stop button)
- "Climatronic" air conditioning system
- Rear headrests (3)
- Reading light front/rear
- Lights: Full LED taillights
- Fatigue detection
- Emergency call service
- Radio: Media System Plus
- Radio accessories: Bluetooth interface with integrated hands-free system and audio streaming
- Wheels: Alloy wheels (4) 7 J x 16" "Design I"
- paddle shifters on the steering wheel
- Power steering
- Seats, passenger seat height adjustable
- Seats: Remote release for folding down the rear seat backrest into the boot
- Seats: Rear seat backrest asymmetrically split and foldable
- Start-stop system and recuperation
- Power outlet: 12V socket at the front
- Variable luggage compartment floor
- Lashing eyes in the luggage compartment
- Central locking with remote control



Extra equipment

- Swiveling tow bar
- Luggage partition net
- Lights: Full LED headlights (Full LED headlights - "Hola!" light projection for greeting under the exterior mirrors - Dynamic headlight range control - Rear turn signals with dynamic LED technology Infinite Light; Dynamic LED light strip at the rear)
- Package: Dinamica - Package (Seat center section in Dinamica microfiber, color black - Driver's seat electrically adjustable with memory function - Lumbar support driver's side, electrically adjustable - Exterior mirrors with memory function - Rear center armrest with pass-through option)
- Package: Light and Sight (Rain sensor - Automatically dimming interior mirror - Light sensor with automatic headlight control - Automatic coming home and leaving home function)
- Deletion of the model designation on the rear
- Paint finish: Metallic
- Navigation system (prepared for activation of the SEAT CONNECT online infotainment service package - navigation system with 10" display - 3D navigation - voice control - MAPCARE with integrated map for Europe, Wireless Full Link Connectivity incl. Android Auto and Apple CarPlay)
- Package: Driving Assistance Package M for navigation system (Adaptive Cruise Control up to 210 km/h with predictive speed control PCC - High Beam Assist - Traffic Sign Recognition)
- Park Assist with front parking aid
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Virtual Cockpit (Fully digital instrument cluster with 10.25" TFT display)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der montierte Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 2: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 2: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 3: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 3: Vehicle glazing: Windscreen - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VSSZZZKL0PR034372

Hersteller / Modell: SEAT SEAT Leon Sportstourer 2.0 TDI DSG Style

Datum	KM-Stand	Beschreibung
21.08.2025	45.863	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
12.11.2024	31.888	Regelwartungsdienst
08.05.2024	22.704	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges