



Porsche Panamera:				
Vinnumber:	WP0ZZZ97ZNL125213	Versionname:		
First Registrationdate:	14/02/2022	Fiscalpower:		
Expertise Mileage:	133403	Power Kw:		
Bodytype:		Body colour	Blue	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3733	
Fueltype:	Hybrid Petrol			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Seats electric F R		
Steering wheel multifunctional		Sun Roof electric		
Seats F heated		Panoramic roof		
Radio multimedia		Luggage cover		
Type of headlighting	Headlighting LED	Front parking sensors		
Type of GPS	GPS big screen color	Rear parking sensors		
Type of Lining	Lining leather	Type of Tow bar	No Tow bar	
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
	265/45/19/105 Y			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				265/45 R 19 105 Y
Tyre size FR				265/45 R 19 105 Y
Tyre size RL				295/40 R 19 108 Y
Tyre size RR				295/40 R 19 108 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Number of charging cables (normal)	1			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				2500,22
Interior, Worn, Acceptable				0,00



Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------



Bumper moulding F, Scratch(es), Replace	466,61
---	--------




Bonnet, Chemical polution, Polish	0,00
-----------------------------------	------



Windscreen moulding, Scratch(es), Replace	49,95
---	-------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Charging cable (fast), Missing, Check	0,00
---------------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Rear window, Scratch(es), Replace

1640,34



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03



Outside rear-view mirror housing R, Scratch(es), Polish

77,26



Alloy rim RR, Scratch(es), Repair and paint (complete)

133,03

