


DEKRA Automotive Solutions

Vehicle details

VIN	VSSZZZKL1 RR099170	Mileage	59 817 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2FKD498	Registration date	29/05/2024	Engine size	1498
Brand	CUPRA	Fuel level	-	Transmission	Automatic
Model	LeonST-2013	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Noir		

Inspection Details

Inspection date	17/06/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique
-----------------	------------	-----------------	---------------------------	-------------	------------------------



Other technical information

Emergency compressor kit	✓	Service manual holder	✓
Refill emergency kit	✓	User manual	✓
Triangle	✓	Key	✓
Safety vest	✓		
Fire extinguisher	✓		
Towing hook	✓		
Load cover	✗		

Options / Equipment

Tyres

Uniroyal 225/40/18 Y Summer 6.0 mm		Uniroyal 225/40/18 Y Summer 6.0 mm	
Bridgestone 225/40/18 Y Summer 5.0 mm		Bridgestone 225/40/18 Y Summer 5.0 mm	

Damages

1		Part	Load cover	2		Part	Selt Belt cover guide
		Position	-			Position	Back right
		Damages	Missing			Damages	Misaligned
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	Adjust
							sous reserve d echange

DEKRA Automotive Solutions

3		Part Position Damages Severity Repair mode	Bumper Front right Dent & Chips - Repair	4		Part Position Damages Severity Repair mode	Wing Front left Dented - Smart Repair
5		Part Position Damages Severity Repair mode	Special rim 18" Front left Scratched - Smart Repair	6		Part Position Damages Severity Repair mode	Fabric seat Front left Stained/dirty - Cleaning
7		Part Position Damages Severity Repair mode	Special rim 18" Back left Scratched - For info	8		Part Position Damages Severity Repair mode	Bumper Back left Scratched - Smart Repair
9		Part Position Damages Severity Repair mode	Tailgate / Boot door Back Dented - For info	10		Part Position Damages Severity Repair mode	Wing Back right Dented - For info
11		Part Position Damages Severity Repair mode	Special rim 18" Back right Scratched - Smart Repair	12		Part Position Damages Severity Repair mode	Door Front right Dented - For info
13		Part Position Damages Severity Repair mode	Special rim 18" Front right Scratched - Smart Repair	14		Part Position Damages Severity Repair mode	Door Front left Chemical deposit - Polishing
15		Part Position Damages Severity Repair mode	Door Back left Chemical deposit - Polishing				