MACADAM










Opel Corsa: N694LR

Vinnumber:	**VXKUHZKXZM4303106**	Versionname:	**Corsa-E 3 fase lader 100kW / 50kWh Edition**
First Registrationdate:	**17/11/2021**	Fiscalpower:	
Expertise Mileage:	**86990**	Power Kw:	**100**
Bodytype:		Body colour	**White Jade**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Electric**	Parking lot	**497**
Number of seats	**5**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**
Autom climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 91 / H / Steel	4,6 mm	Continental	All season
	Right	195 / 55 / 16 / 91 / H / Steel	4,0 mm	Continental	All season
Rear	Left	195 / 55 / 16 / 91 / H / Steel	7,0 mm	Continental	All season
	Right	195 / 55 / 16 / 91 / H / Steel	6,8 mm	Continental	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Wing RL, Dent(s), Repair and paint (complete)





Side window trim RL, Scratch(es), Replace




Door FL, Bad repair, Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)




Bumper grille, Deformed / Strained, Replace




Door RR, Bad repair, Repair and paint (complete)




Rear spoiler, Dent(s), Repair and paint (complete)





Onderhoudshistorie van: VXKUHZKXZM4303106

ALPHABET

Kenteken	N694LR
Merk Model	Opel Corsa-E 3 fase lader 100kW / 50kWh Edition
Brandstofsoort	Elektrisch
Datum deel1	11/17/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
4/19/26	0	Ruitenwisserblad(en) achterzijde
10/16/25	71,910	Accu
10/16/25	71,910	APK
10/16/25	71,910	Ruitenwisserblad(en) voorzijde
3/20/25	68,245	Vervanging band
1/3/25	68,240	Onderhoudsbeurt
2/16/24	48,274	Vervanging band
11/16/23	44,337	On Board Charger
11/16/23	44,337	Onderhoudsbeurt
11/16/23	44,337	Remvloeistof
3/1/23	22,232	Onderhoudsbeurt
10/26/22	14,828	Onderhoudsbeurt