



Audi A

Vinnumber:	WAUZZZGY6MA028041	Versionname:	
First Registrationdate:	4/06/2021	Fiscalpower:	
Expertise Mileage:	140152	Power Kw:	81
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2830
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/45/17/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 17 92 H
Tyre size FR				225/45 R 17 92 H
Tyre size RL				225/45 R 17 92 H
Tyre size RR				225/45 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				265
Tyre make RL				255
Tyre make RR				265

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1845,07
Seat cover FL, Damaged, Acceptable	0,00



Bumper F, Scratch(es), Repair and paint (complete)	296,58
--	--------




Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Alloy rim FL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)	415,60
--	--------




Door FR, Dent(s) and scratch(es), Repair and paint (complete)	505,30
---	--------



Wing RR, Dent(s), Paintless dent repair	95,47
---	-------



Alloy rim RR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------

