



Expertise

Protocol number: 46800753
Order No. / Reference: 26754738
Inspection date: 30 Jul 2026

Manufacturer: Audi
VIN: WAUZZZGE1MB029551

Model: e-tron 55 quattro S line



Vehicle details	
Manufacturer / Type / Model / Equipment	
Audi e-tron 55 quattro S line	
Vehicle Identification number	WAUZZZGE1MB029551
Mileage (Read)	131,671 km
First registration	27 Apr 2021
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Electric
Power	158 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Brillantschwarz (Y9B)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	18,000 km
Last service on / at	11/2025 at 119,632 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA768796
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0588 / BSL 00063		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	3,170 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	265/45 R21 108H	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	265/45 R21 108H	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/55 R19 111H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	255/55 R19 111H	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Acoustic vehicle warning system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service with Audi connect Remote & Control
- Exterior mirror housings painted in body color
- third brake light
- Parking aid plus with surround view
- Electronic Stability Control (ESC)
- key fob
- Removable luggage compartment cover
- Cruise control system including speed limiter
- Heated rear window
- Interior lighting
- ISOFIX child seat anchors for front passenger seat
- 2-zone automatic climate control
- Headrests (2) height adjustable
- CCS Type 2 charging socket
- Charging cable with industrial plug CEE 16A / 400V / 6 h / long + straight
- Steering wheel: Double-spoke leather steering wheel with multifunction and paddle shifters
- Package: Gloss
- Radio: MMI Navigation plus with MMI touch
- Radio accessories: Audi music interface
- Wheel bolts with anti-theft protection and wheel loosening detection
- Rear seat backrest foldable
- Seat belts
- Sun visor with illuminated makeup mirror on driver and passenger side
- 12-volt sockets
- First aid kit with warning triangle
- Electronic immobilizer
- Central locking
- Airbag: Front side airbags and head airbag system
- All-wheel drive: Quattro
- Audi connect navigation & infotainment
- Audi pre sense basic
- Audi pre sense front
- Vehicle tool kit
- Decorative inlays: Fine lacquer graphite grey
- Door sills with aluminum inlay, front and rear, illuminated
- Chassis: adaptive air suspension sport
- front and rear floor mats
- Electrically opening and closing tailgate
- Transmission: 1-speed direct drive
- rear window wiper
- Interior mirror with automatic dimming, frameless
- ISOFIX child seat attachment and Top Tether for the rear seat
- Paint finish: Solid
- Charging cable with household plug
- Standard charging cable length
- e-tron compact charging system
- front center armrest
- On-board charger up to 11 kW (AC)
- Progressive steering
- Radio: MMI Radio plus with MMI touch response
- Radio accessories: Digital radio reception (DAB)
- Tire pressure monitoring system
- Tire repair kit
- Headlight cleaning system
- Seats: Front seats manually adjustable
- Lane Departure Warning
- Stationary air conditioning
- Separation net
- Glazing: Front window in acoustic glazing
- thermal insulation glazing

Extra equipment

- Audi virtual cockpit plus (with Classic, e-tron and Sport design display options; innovative, fully integrated 12.3" instrument cluster for flexible and needs-based display of the respective information according to the driver's requirements: speed/power demand, map display, Audi connect services, radio/media information, etc. Operation via the multifunction steering wheel. Navigation map displayed as a 3D terrain model; permanent display of navigation information in the speedometer area when route guidance is active; including break recommendation)
- Deletion of model designation and performance/technology lettering
- Chassis: adaptive air suspension (electronically controlled air suspension with continuously adaptive damping system at all 4 wheels automatically regulates vehicle level and damping including level control and manual lift function; setting of various modes via Audi drive select)
- Charging cable with industrial plug CEE 16A / 400V (mains connection cable (length 0.9 m) with industrial plug 3-phase, red, angled design)
- e-tron connect charging system up to 22 kW (The e-tron connect charging system is a mobile Mode 2 charging system and includes a control unit, a vehicle connection cable of selectable length (2.5 m standard or 7.5 m optional) and 2 mains connection cables (household and industrial plugs) - Cost-optimized charging - Integrated charging energy monitoring - Solar power utilization - Blackout protection - PIN protection - Software updates)
- Steering wheel: Sport leather steering wheel with multifunction and paddle shifters (paddle shifters allow manual changing of the driving modes.)
- Package: Ambient Lighting Package (Roof module front/rear incl. reading lights (capacitively switched) - Illuminated vanity mirrors for driver and front passenger - Entry lights on the underside of the doors front/rear - Glove compartment lighting - Footwell lighting front/rear - Trunk lighting right/left - Approach lighting from the tailgate. In addition to the standard interior lighting (white light): - Ambient fabric panel lighting of the doors front/rear - Approach lighting from the exterior door handles front/rear - Ambient lighting center console front.)
- QQ1
- Wheel: Alloy wheels, 21" 5-arm turbine, black, diamond-turned (9.5 J x 21, 265/45 R21 tires)
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound (sound reproduction via 16 speakers including 3D sound speakers, center speaker and subwoofer, 15-channel amplifier with a total output of 705 watts; spatial sound reproduction thanks to the 3D sound feature for the front seats. This is created by additional speakers in the A-pillars, the midrange speakers and Fraunhofer Symphoria technology. The 3D sound can be played back with all sources.)
- Electrically adjustable, heated, and folding exterior mirrors with automatic dimming on both sides (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, convex, flat, or aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb).
- Decorative inlays: Dark brushed matt aluminum
- Anti-theft alarm system (Monitors doors, front and trunk lid - Ultrasonic interior monitoring can be deactivated - Warning in case of theft via tilt sensor - Battery-powered horn - Safelock prevents doors from being opened from the inside once the vehicle has been locked with the vehicle key.)
- Comfort center armrest in the front (adjustable in tilt and longitudinally movable)
- Charging clip (The convenient wall mount for the e-tron charging system offers the possibility to neatly and conveniently attach the charging cable at frequently used charging locations (e.g., garage wall). The vehicle connector is properly stored in the included connector holder. This can be mounted separately from the wall mount.)
- LED matrix headlights, LED taillights (with the following functionalities: - Daytime running lights - Low beam - High beam - Position lights - Dynamic turn signals - Cornering lights - All-weather lights - Maneuvering lights - Highway lights - Automatic dynamic headlight range control)
- Black Optics Package (adds black accents to the exterior in the area of the Audi Singleframe grille, the trim strips on the side windows, and the front and rear bumpers. Design varies depending on the model and equipment.)
- Package: Interior S line (Sport seats in front in Alcantara/leather combination with contrast stitching and S embossing in the backrests of the front seats - Sport leather steering wheel with multifunction and shift paddles including steering wheel grips in perforated leather, S line emblem and chrome application - Decorative inlays in matt brushed dark aluminum - Door sill trims with aluminum inlay front and rear, illuminated, front with S lettering - Headliner in black fabric - Floor mats front and rear with contrast stitching)
- Wheel: Winter alloy wheels, 19" 5-arm aero, with graphic print (8 J x 19, 255/55 R19 tires suitable for snow chains)
- Reversing camera (image of the area behind the vehicle displayed on the MMI screen. Dynamic display elements such as a steering angle-dependent lane guidance assist with parking and maneuvering. The reversing camera is discreetly integrated into the tailgate handle. Activation is achieved by engaging reverse gear, via a button in the center console, or a button on the upper screen, provided the distance indicator is displayed.)



- Seat covers in Alcantara Frequency/leather combination (center section of the front seats and the two outer rear seats in Alcantara Frequency black or rotor grey; side bolsters, headrests, middle rear seat and front center armrest in leather black or rotor grey with S embossing in the backrests of the front seats)
- Seats: Front sports seats (with manual adjustment of seat height, seat longitudinal position, seat tilt, backrest tilt, headrest height and distance and belt height with pronounced seat side bolsters for better lateral support in curves, extendable thigh support and electric 4-way lumbar support)
- Telephone: Audi Phone Box (Up to two smartphones can be paired with the vehicle simultaneously via Bluetooth, allowing you to play music through the vehicle or make phone calls from either smartphone. The universal smartphone holder connects to the vehicle's antenna, improving both reception and call quality. The smartphone can also be charged wirelessly using the Qi standard or via USB.)
- Dashboard top and interior elements at the bottom in synthetic leather (dashboard top in black synthetic leather with tone-on-tone stitching - armrest in the doors and center console at the bottom in synthetic leather color-matched to the respective interior color - in conjunction with S line interior or for S models with contrast stitching)
- Front seat heating (heats seat and backrest center section, also seat side bolsters with leather upholstery and sports seats, individually adjustable in multiple stages for driver and passenger side)
- Stationary climate control comfort (cools or heats the interior to a desired temperature before driving, ensuring climate comfort from the moment you enter the vehicle. Additionally, seat heating and ventilation, steering wheel heating, and glass surface heating can also be activated before driving if these optional features have been selected. Programmable or activatable via MMI or smartphone app, regardless of whether the vehicle is charging at the time.)
- Glazing: Privacy glazing (tinted windows) (rear window, rear door and side windows tinted)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door - Scratch(es) - Cover / polish
2	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
3	Front bumper	Front bumper - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Replacement engines

No.	Replacement engine
1	Replacement engine, Installation date 11 Dec 2025, at -Status 119,636



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Fahrzeug weist dem Alter und Laufleistung entsprechende Gebrauchspuren auf.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 1: Door - front left side: Door - Scratch(es) - Cover / polish



Damage 1: Door - front left side: Door - Scratch(es) - Cover / polish



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper - Stone chips - Paint




Damage 3: Front bumper: Front bumper - Stone chips - Paint



Damage 3: Front bumper: Front bumper - Stone chips - Paint



Damage 3: Front bumper: Front bumper - Stone chips - Paint




Damage 3: Front bumper: Front bumper - Stone chips - Paint



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 2: Bonnet: Bonnet - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WAUZZZGE1MB029551
Hersteller / Modell: AUDI AUDI e-tron 55 quattro S line

Datum	KM-Stand	Beschreibung
11.12.2025	119.636	Motor ern; Reparatur Sonstiges; Systemtest/Eigendiagnose
14.11.2025	119.632	Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
18.08.2025	112.730	Bremsbelagfühler ern; Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremssscheiben + Klötze h; Bremssscheiben + Klötze v; Bremssscheiben hinten; Bremssscheiben vorne
07.03.2025	99.359	Systemtest/Eigendiagnose; Wartung Sonstiges
10.01.2025	95.537	Systemtest/Eigendiagnose
04.10.2024	88.436	Regelwartungsdienst; Wartung Sonstiges
11.08.2023	58.574	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
17.06.2022	30.714	Regelwartungsdienst; Wartung Sonstiges