

2-DDU-228

2-DDU-228 · Move! 1.0 TSI 95cv 5v unicolor · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DDU-228	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ5PR085204
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	Move! 1.0 TSI 95cv 5v unicolor	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	15-02-2023
Color	Grey	Odometer	78.992 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	70	Number Headrests	5





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Seat heating

Steering wheel multifunction

Condition

Condition exterior

Adequate

Maintenance Remarks Olieverversen

Condition interior

Adequate

Previous Repairs

Unknown

Last Maintenance Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part

Fender – Front Right



Damage Type

Dislocated / Loose



Repair Type

Repair



Acceptable

No



Damage Part

Roof



Damage Type

Small dent(s)

Notes

Dakstijl

Repair Type

Restyle

Acceptable

No



Damage Part

Windscreen – Front



Damage Type

Chipped

Repair Type

Window Repair

Acceptable

No



Damage Part

Fender – Front Right



Damage Type

small dents / small scratches



Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Tailgate	Missing	Kapje ruitenwisser	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Left	Small dent(s)	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Scratch(es)	En ontzet	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Compressor	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No