



Peugeot 3008 (UKL): 2BSL740

Vinnnumber:	VF3MCYHZUMS268780	Versionname:	3008 Allure Pack 1.5 BlueHDi S&S 130pk/cv 5p EAT8
First Registrationdate:	8/03/2022	Fiscalpower:	
Expertise Mileage:	107963	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	plus 13800 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/55/18/102 Y			
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 Y
Tyre size RR				225/55 R 18 102 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Backrest cover FR, Scratch(es), Acceptable			



Roof liner, Hole, Smart repair



Seat cover FL, Worn, Acceptable



Engine insulation, Hole, Replace




Bumper F, Scratch(es), Repair and paint (complete)




Bonnet, Scratch(es), Repair and paint (complete)



Alloy rim FL polished, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Mirror side repeater L, Scratch(es), Acceptable



Boot carpet, Damaged, Smart repair



Alloy rim FR polished, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Roof, Dent(s), Acceptable



Kenteken	2BSL740
Merk Model	Peugeot 3008 Allure Pack 1.5 BlueHDi S&S 130pk/cv 5p EAT8
Brandstofsoort	Diesel
Datum deel1	3/8/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/9/25	91,804	90000 km	Uitvoeren
12/9/25	91,804	oliezeef	Vervangen
12/2/24	69,461	60000 km	Uitvoeren
12/2/24	69,461	brandstof hoofdfilter	Vervangen
12/2/24	69,461	luchtfilter	Vervangen
12/2/24	69,461	luchtfilter interieur	Vervangen
12/2/24	69,461	oliezeef	Vervangen
12/2/24	69,461	remblokken achter	Vervangen
10/13/23	44,000	45000 km	Uitvoeren
10/13/23	44,000	oliezeef	Vervangen
2/3/23	22,644	20000 km	Uitvoeren
2/3/23	22,644	oliezeef	Vervangen