



PEUGEOT 308 SW: GG-254-ER

Vinnumber:	VR3FCYHZTNY537266	Versionname:	PEUGEOT 308 SW BlueHDi 130 EAT 8 GT VP [5P] bva 8-130CH-7cv (break)
First Registrationdate:	6/05/2022	Fiscalpower:	
Expertise Mileage:	94735	Power Kw:	96
Bodytype:	Break	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	
Type of climate control	Autom climate control		Lining Other Lining Semi-leather Lining Alcantara

Tyres

	225/45/18/92 Y			
Summer tyres:	Fr.L.	Goodyear: 70%	Fr.R.	Goodyear: 70%
	Re.L.	Hankook: 30%	Re.R.	Hankook: 25%
Tyre profile depth FL				3.8
Tyre profile depth FR				3.8
Tyre profile depth RL				6.3
Tyre profile depth RR				6.5
Tyre size FL				225/45 R 18 92 Y
Tyre size FR				225/45 R 18 92 Y
Tyre size RL				225/45 R 18 92 Y
Tyre size RR				225/45 R 18 92 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Remote ignition key (no insert), Missing, Repair/replace (lump sum)			



Interior, Dirty, Cleaning



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Tear, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Door FR, Scratch(es), Paint



Historique Maintenance

Immatriculation: GG-254-ER Date de 1ère immatriculation: 06/05/2022

Modèle: Peugeot 308 SW BlueHDi 130 EAT 8 GT VP [5P] bva 8-130CH-7cv (break)

Date	Kilométrage	Fournisseur	Descriptif
09/06/2026	93.222	DEKRA AUTOMOTIVE TRAPPES	CONTROLE TECHNIQUE
27/02/2026	89.177	VERBAERE AUTOMOBILES	ADBLUE
			LIQUIDE DE FREIN
			REVISION
			DIVERS CLIM
			DIVERS ELEC
23/06/2025	76.691	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
30/01/2025	67.769	VERBAERE AUTOMOBILES	FILTRE A AIR RPLT
			REVISION
			FILTRE CLIM RPLT
			REVISION
			ANTIBROUILLARD RPLT
25/09/2024	59.650	FLEET SOLUTIONS FRANCE	PLAQUETTES AV RPLT
21/09/2024	58.651	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
26/01/2024	47.280	VERBAERE AUTOMOBILES	LIQUIDE DE FREIN
			REVISION
			FILTRE CLIM RPLT
29/11/2023	42.284	NORAUTO SAS (PRODUIT SPE)	GARDIENNAGE
			PERMUTATIONS PNEUS
22/05/2023	24.248	NORAUTO SAS (PRODUIT SPE)	PERMUTATIONS PNEUS
			GARDIENNAGE
12/04/2023	22.402	STELLANTIS &YOU FRANCE SAS	RECYCLAGE
			BALAI ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			FILTRE CLIM RPLT
			REVISION
02/01/2023	14.310	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER
02/11/2022	9.004	NORAUTO SAS (PRODUIT SPE)	GARDIENNAGE
			REPARATION DE ROUE
			REPLACEMENT PNEUS HIVER
19/08/2022	1.189	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS ETE