



FORD Kuga: 3395-MFW

Vinnumber:	WF0FXXWPMHNG15562	Versionname:	ST-Line X 2.5 Duratec FHEV 140kW 4x4 Aut
First Registrationdate:	29/03/2023	Fiscalpower:	tototerreno 140kW 5P automática
Expertise Mileage:	241049	Power Kw:	
Bodytype:	SUV	Body colour	White
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Radio
Number keys remote	2	Seats electric F L
GPS big screen color		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		Roof bar black
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	245/45/20/103 Y			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/45 R 20 103 Y
Tyre size FR				245/45 R 20 103 Y
Tyre size RL				245/45 R 20 103 W
Tyre size RR				245/45 R 20 103 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Door panel RR, Scratch(es), Replace			



Boot lid covering R, Scratch(es), Replace



User's manual, Missing, Repair/replace (lump sum)



Service book, Missing, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Broken, Repair and paint (complete)



Bumper moulding FL, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Door RR, Dent(s), Repair and paint (complete)



Wing trim RR, Scratch(es), Acceptable



Internal boot lining L, Tear, Replace



Bumper R, Scratch(es), Acceptable



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering



Roof, Scratch(es), Repair and paint (complete)



Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller

Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller