



Ford Focus (UKL): 2BVG662

Vinnumber:	WF0PXXGCHPNS40363	Versionname:	Focus Clipper Connected 1.5d EcoBlue 120pk/cv 5p
First Registrationdate:	5/04/2022	Fiscalpower:	
Expertise Mileage:	183593	Power Kw:	88
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/60/16/92 V			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Stain, Acceptable



Floor covering FL, Hole, Acceptable



Door panel FL, Worn, Acceptable



Bumper F, Repaired, Acceptable



Door FL, Dent(s) and scratch(es), Spot repair



Wing RL, Repaired, Check



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Repaired, Check



Bumper R, Repaired, Check



Rear window, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Door seal RR, Broken, Replace



Sill trim R, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Kenteken	2BVG662
Merk Model	Ford Focus Clipper Connected 1.5d EcoBlue 120pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	4/5/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/28/25	155,947	luchtfILTER interieur	Vervangen
10/28/25	155,947	oliezeef	Vervangen
10/28/25	155,947	ruitenwisserrubber achter	Vervangen
10/28/25	155,947	ruitenwisserrubber vooraan	Vervangen
10/28/25	155,947	universele lampen	Vervangen
7/31/25	143,967	distributieriem en spanner	Vervangen
7/31/25	143,967	remschijven en blokken achter	Vervangen
2/28/25	124,175	120000 km	Uitvoeren
2/28/25	124,175	brandstof hoofdfilter	Vervangen
2/28/25	124,175	luchtfILTER	Vervangen
2/28/25	124,175	luchtfILTER interieur	Vervangen
2/28/25	124,175	oliezeef	Vervangen
2/28/25	124,175	ruitenwisserrubber achter	Vervangen
2/28/25	124,175	ruitenwisserrubber vooraan	Vervangen
7/9/24	93,130	90000 km	Uitvoeren
7/9/24	93,130	luchtfILTER	Vervangen
7/9/24	93,130	oliezeef	Vervangen
7/9/24	93,130	remblokken achter	Vervangen
7/9/24	93,130	remblokken vooraan	Vervangen
7/9/24	93,130	remvloeistof	Vervangen
10/20/23	60,146	60000 km	Uitvoeren
10/20/23	60,146	brandstof hoofdfilter	Vervangen
10/20/23	60,146	luchtfILTER	Vervangen
10/20/23	60,146	luchtfILTER interieur	Vervangen
10/20/23	60,146	oliezeef	Vervangen
10/20/23	60,146	ruitenwisserrubber achter	Vervangen
10/20/23	60,146	ruitenwisserrubber vooraan	Vervangen
3/1/23	30,463	30000 km	Uitvoeren
3/1/23	30,463	luchtfILTER	Vervangen
3/1/23	30,463	oliezeef	Vervangen
3/1/23	30,463	ruitenwisserrubber vooraan	Vervangen