

New for old value (N)

Remarks

Next ...

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number				Code / Agency				Date accident 25/06/2026							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 25/06/2026		Date first survey 29/06/2026		Place Foggia		C/O		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) TOYOTA HILUX 2.4 D-4D M/T SC 4WD Comfort								Plate GM549VX		Vin Chassis AHTKB3CB202373453				First Registration 16/02/2023							
Usage status NON CONOSCIUTO		Km 54230		Tyres % 50		Color Bianco		Type of enamel PASTEL				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0		Wheelbase								Seats No. 0		Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations										SR		LA		VE		ME		D.M. S.C.		Costs of spare parts	
										Dif Time		Dif Time		Dif Time		Time				* (VAT excluded)	
1		61132KK020		Front pillar with partial structure of door compartment				L		L		L									
1		Codice Ricambio		Riquadratura/raddriz. parte ant.re				L				M									
1		Codice Ricambio		Ripristino cablaggi ant.				L													
1		Codice Ricambio		Equilibratura e convergenza																	
1		Codice Ricambio		Reset centraline/azz. errori/ricerca guasti																	
1		Codice Ricambio		Rimozione adesivi																	
1		Codice Ricambio		N.3 cerchi ruota_PRM																	
1		Codice Ricambio		N.3 pneum_PRM																	
1		Codice Ricambio		Volante_PRM																	
1		Codice Ricambio		Paraurti post_PRM																	
1		Codice Ricambio		--- NOTE ---																	
1		Codice Ricambio		Mezzo non marciante, non avviabile e dotaz. int. non test.																	
1		Codice Ricambio		Quantificati i danni visibili e/o potenzialmente																	
1		Codice Ricambio		correlati con quanto rilevabile.																	

New for old value (N)	Remarks Pneum. Michelin 225/75 R17. Mezzo sporco. Computo integrato con preventivo fornitori; note in corpo di perizia.
-----------------------	--