

INSPECTION REPORT

End of contract

GENERAL INFO

File	309803
License plate	2BLF777
Vehicle identification number	SB1Z93BE20E272399
Dossier	2021 274 036
Make	Toyota Corolla TS 1.8 Hybrid D
Mileage	53947
First registration	03/01/2022
client availability date	02/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	



DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
153	Rear Bonnet // Painting	Y
331	Wheel Alloy Rear Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures




Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Front // Repair & Painting-scratch + dent

